

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/09/2022

Submitted Date:

05/09/2022

Document Number:

702400412

**FIELD INSPECTION FORM**

Loc ID 336337 Inspector Name: Revas, Robbie On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 10633  
Name of Operator: CRESTONE PEAK RESOURCES OPERATING LLC  
Address: 1801 CALIFORNIA STREET #2500  
City: DENVER State: CO Zip: 80202

**Findings:**

15 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

| Contact Name | Phone | Email                         | Comment                         |
|--------------|-------|-------------------------------|---------------------------------|
| ,            |       | Inspections@civiresources.com | <a href="#">All Inspections</a> |

**Inspected Facilities:**

| Facility ID | Type                  | Status | Status Date | Well Class | API Num   | Facility Name        | Insp Status |
|-------------|-----------------------|--------|-------------|------------|-----------|----------------------|-------------|
| 294580      | WELL                  | PR     | 02/01/2022  | GW         | 123-25501 | RAY NELSON 13-32     | PR          |
| 294594      | WELL                  | SI     | 03/01/2021  | GW         | 123-25514 | RAY NELSON 24-32     | SI          |
| 294595      | WELL                  | PR     | 02/01/2022  | GW         | 123-25515 | RAY NELSON 14-32     | PR          |
| 462443      | OFF-LOCATION FLOWLINE | AC     | 03/31/2021  |            | -         | Wellhead Line 32SWSW | AC          |
| 462466      | OFF-LOCATION FLOWLINE | AC     | 03/31/2021  |            | -         | Wellhead Line 32SWSW | AC          |
| 462467      | OFF-LOCATION FLOWLINE | AC     | 03/31/2021  |            | -         | Wellhead Line 32SWSW | AC          |
| 473074      | OFF-LOCATION FLOWLINE | AC     | 03/31/2021  |            | -         | Wellhead Line 32SWSW | AC          |

**General Comment:**

**Location**

Overall Good:

**Signs/Marker:**

|                    |                      |       |  |
|--------------------|----------------------|-------|--|
| Type               | BATTERY              |       |  |
| Comment:           | adequate             |       |  |
| Corrective Action: |                      | Date: |  |
| Type               | WELLHEAD             |       |  |
| Comment:           | adequate x 3         |       |  |
| Corrective Action: |                      | Date: |  |
| Type               | TANK LABELS/PLACARDS |       |  |
| Comment:           | adequate             |       |  |
| Corrective Action: |                      | Date: |  |

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good:

**Spills:**

| Type | Area | Volume |  |  |
|------|------|--------|--|--|
|      |      |        |  |  |

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

|                    |                                     |       |  |
|--------------------|-------------------------------------|-------|--|
| Type               | IGNITOR/COMBUSTOR                   |       |  |
| Comment:           | Chainlink topped with barb wire     |       |  |
| Corrective Action: |                                     | Date: |  |
| Type               | TANK BATTERY                        |       |  |
| Comment:           | Chainlink topped with barb wire     |       |  |
| Corrective Action: |                                     | Date: |  |
| Type               | WELLHEAD                            |       |  |
| Comment:           | Chainlink topped with barb wire x 3 |       |  |
| Corrective Action: |                                     | Date: |  |

**Equipment:**

|                               |                            |       |                 |
|-------------------------------|----------------------------|-------|-----------------|
| Type: Emission Control Device | # 3                        |       | corrective date |
| Comment:                      |                            |       |                 |
| Corrective Action:            |                            | Date: |                 |
| Type: Bradenhead              | # 3                        |       |                 |
| Comment:                      | all are exposed at surface |       |                 |
| Corrective Action:            |                            | Date: |                 |
| Type: Flow Line               | # 5                        |       |                 |

|                                   |                                    |  |       |
|-----------------------------------|------------------------------------|--|-------|
| Comment:                          |                                    |  |       |
| Corrective Action:                |                                    |  | Date: |
| Type: Horizontal Heated Separator | # 1                                |  |       |
| Comment:                          |                                    |  |       |
| Corrective Action:                |                                    |  | Date: |
| Type: Plunger Lift                | # 3                                |  |       |
| Comment:                          |                                    |  |       |
| Corrective Action:                |                                    |  | Date: |
| Type: Ancillary equipment         | # 9                                |  |       |
| Comment:                          | automation                         |  |       |
| Corrective Action:                |                                    |  | Date: |
| Type: Bird Protectors             | # 4                                |  |       |
| Comment:                          |                                    |  |       |
| Corrective Action:                |                                    |  | Date: |
| Type: Gas Meter Run               | # 1                                |  |       |
| Comment:                          | card indicates current calibration |  |       |
| Corrective Action:                |                                    |  | Date: |

**Tanks and Berms:**

| Contents           | # | Capacity | Type           | Tank ID | SE GPS |
|--------------------|---|----------|----------------|---------|--------|
| PRODUCED WATER     | 1 | OTHER    | FIBERGLASS AST |         | ,      |
| Comment:           |   |          |                |         |        |
| Corrective Action: |   |          |                |         | Date:  |

Paint

|                  |         |
|------------------|---------|
| Condition        |         |
| Other (Content)  |         |
| Other (Capacity) | 150 bbl |
| Other (Type)     |         |

Berms

| Type               | Capacity                                 | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|--|---------------------|---------------------|-------------|
| Metal              | Adequate                                 | Walls Sufficient    | Base Sufficient     | Adequate    |
| Comment:           | shares containment with condensate tanks |                     |                     |             |
| Corrective Action: |  |                     |                     | Date:       |

| Contents           | # | Capacity | Type      | Tank ID | SE GPS                |
|--------------------|---|----------|-----------|---------|-----------------------|
| CONDENSATE         | 3 | OTHER    | STEEL AST |         | 40.090840,-105.032620 |
| Comment:           |   |          |           |         |                       |
| Corrective Action: |   |          |           |         | Date:                 |

Paint

|                  |          |
|------------------|----------|
| Condition        | Adequate |
| Other (Content)  |          |
| Other (Capacity) | 330 bbl  |

|                    |  |
|--------------------|--|
| Other (Type) _____ |  |
|--------------------|--|

**Berms**

| Type               | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|----------|---------------------|---------------------|-------------|
| Metal              | Adequate | Walls Sufficent     | Base Sufficient     | Adequate    |
| Comment:           |          |                     |                     |             |
| Corrective Action: |          |                     |                     | Date:       |

**Wells Served By Facilities Above**

| API Number |
|------------|
| 123-25514  |
| 123-25515  |
| 123-25501  |

**AirsID**

| API Number | AirsID |
|------------|--------|
|            |        |

**Venting:**

|                    |    |       |  |
|--------------------|----|-------|--|
| Yes/No             | NO |       |  |
| Comment:           |    |       |  |
| Corrective Action: |    | Date: |  |

**Flaring:**

|                    |  |       |
|--------------------|--|-------|
| Type               |  |       |
| Comment:           |  |       |
| Corrective Action: |  | Date: |

**Inspected Facilities**

Facility ID: 294580 Type: WELL API Number: 123-25501 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR  
 Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**BradenHead**

Date of Last Brhd Test: 03/23/2022 Annual Brhd Completed? Yes  
 Last Brhd Test Results Initial Surf Csg Pressure: 46 Fluid Type: \_\_\_\_\_  
 End Surf Csg Pressure: 0  
 Comment: \_\_\_\_\_  
 Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Facility ID: 294594 Type: WELL API Number: 123-25514 Status: SI Insp. Status: SI

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_  
 Comment: SI  
 Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**BradenHead**

Date of Last Brhd Test: 03/23/2022 Annual Brhd Completed? Yes  
 Last Brhd Test Results Initial Surf Csg Pressure: 42 Fluid Type: \_\_\_\_\_  
 End Surf Csg Pressure: 0  
 Comment: \_\_\_\_\_  
 Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Facility ID: 294595 Type: WELL API Number: 123-25515 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR  
 Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**BradenHead**

Date of Last Brhd Test: 09/02/2021 Annual Brhd Completed? Yes  
 Last Brhd Test Results Initial Surf Csg Pressure: 37 Fluid Type: \_\_\_\_\_  
 End Surf Csg Pressure: 0  
 Comment: \_\_\_\_\_  
 Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Facility ID: 462443 Type: OFF- API Number: - Status: AC Insp. Status: AC

Facility ID: 462466 Type: OFF- API Number: - Status: AC Insp. Status: AC

|              |        |       |      |             |   |         |    |               |    |
|--------------|--------|-------|------|-------------|---|---------|----|---------------|----|
| Facility ID: | 462467 | Type: | OFF- | API Number: | - | Status: | AC | Insp. Status: | AC |
|--------------|--------|-------|------|-------------|---|---------|----|---------------|----|

|              |        |       |      |             |   |         |    |               |    |
|--------------|--------|-------|------|-------------|---|---------|----|---------------|----|
| Facility ID: | 473074 | Type: | OFF- | API Number: | - | Status: | AC | Insp. Status: | AC |
|--------------|--------|-------|------|-------------|---|---------|----|---------------|----|

**Reclamation - Storm Water - Pit**

**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Gravel           | Pass            | Gravel                  | Pass                  |               |                          |         |

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**COGCC Comments**

| Comment  | User   | Date       |
|--|--------|------------|
| <p>COGCC Inspection Report Summary<br/>                     On Monday 5-9-2022 at approximately 1400 hrs. I, Inspector Robbie Revas,<br/>                     Conducted an on-site inspection:<br/>                     Operator: Civitas/Crestone Peak Resources<br/>                     Location name: Ray Nelson 13-32<br/>                     API #05-123-25501<br/>                     County: Weld<br/>                     Weather: Clear.<br/>                     Location: Dry.<br/>                     While there, I observed Multi well pad, 2 wells PR and 1 is SI at the time of inspection.<br/>                     During this inspection, I observed no compliance issues:<br/>                     See attached photos.<br/>                     No follow up site inspection is needed to ensure that the addressed<br/>                     Compliance issues comply with COGCC rules.</p> | revasr | 05/09/2022 |

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description   | URL   |
|--------------|---------------|---|
| 702400413    | location pics | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5748585">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5748585</a> |