

Inspection Photos  
Operator: Simcoe  
API: 067-07195  
Date: 5/9/2022



Photo 1. View of the project area from the well pad entrance facing center.




Photo 2. View of the eastern fill slope from the southeastern corner facing northward. Revegetation is progressing largely with smooth brome. Scattered Canada thistles (~25) observed.



Photo 3. View of the southern project area from the southeastern corner facing westward. Stormwater diversion needs stabilization (Photo 4).



Photo 4. View erosional channeling approximately 2ft wide and deep within the southeastern project area, downslope from diversion in Photo 3.



Photo 5. View of reference area comprised of ponderosa pine forest with gambel oak, Oregon grape, balsamroot, and muttongrass.