

Inspection Photos  
Operator: Simcoe  
API: 067-08357  
Date: 5/9/2022



Photo 1. View of the project area from the southeastern corner facing center.



Photo 2. View of the southern fill slope from the southeastern corner facing westward. Revegetation is progressing largely with smooth brome, western wheatgrass, intermediate wheatgrass, and sand dropseed.



Photo 3. View of the eastern project area from the southeastern corner facing northward. Stormwater diversion needs stabilization (see Photo 4).



Photo 4. View erosional channeling approximately 2ft wide and deep within the eastern project area.



Photo 5. View of reference area comprised of ponderosa pine forest with gambel oak, Oregon grape, balsamroot, and muttongrass.