



**Location**

Overall Good:

**Signs/Marker:**

Type WELLHEAD

Comment: Adequate

Corrective Action:

Date:

**Emergency Contact Number:**

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good:

**Spills:**

Type	Area	Volume

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

Type WELLHEAD

Comment: iron

Corrective Action:

Date:

**Equipment:**

corrective date

Type: Plunger Lift # 1

Comment:

Corrective Action:

Date:

Type: Bradenhead # 1

Comment:

Corrective Action:

Date:

**Venting:**

Yes/No NO

Comment:

Corrective Action:

Date:

**Flaring:**

Type

Comment:

Corrective Action:

Date:

**Inspected Facilities**

Facility ID: 300378 Type: WELL API Number: 123-29702 Status: SI Insp. Status: SI

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: EQUIPMENT ONSITE

Comment:

Corrective Action:  Date:

**COGCC Comments**

Comment	User	Date
Routine Inspection. No corrective actions were observed at the time of inspection. **Weather Conditions: sunny, dry ground	santistb	05/10/2022

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
679604754	Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5749853">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5749853</a>