

Inspection Photos
Location Name: Andrews (Lanyard Water Flood) 23-18
Location ID: 317994



Photo 1 Wellsite.

Photo 2 WH sign

Inspection Photos
Location Name: Andrews (Lanyard Water Flood) 23-18
Location ID: 317994



Photo 3 TB location.

Photo 4 TB signs PW tanks

Inspection Photos
Location Name: Andrews (Lanyard Water Flood) 23-18
Location ID: 317994



Photo 5 locked office/shop building.

Photo 6 PW tanks

Inspection Photos
Location Name: Andrews (Lanyard Water Flood) 23-18
Location ID: 317994



Photo 7 Vertical Separators.

Photo 8 Flow line manifold

Inspection Photos
Location Name: Andrews (Lanyard Water Flood) 23-18
Location ID: 317994



Photo 9 stained ground inside flow line manifold house.

Photo 10 Leaking threads on the Flow line manifold

Inspection Photos
Location Name: Andrews (Lanyard Water Flood) 23-18
Location ID: 317994



Photo 11 Leaking threads on the flow line manifold.

Photo 12 Crude oil tanks

Inspection Photos
Location Name: Andrews (Lanyard Water Flood) 23-18
Location ID: 317994



Photo 13 Stained soil at Vert. Sep. house

Photo 14 inside of Vert. Sep. house

Inspection Photos
Location Name: Andrews (Lanyard Water Flood) 23-18
Location ID: 317994



Photo 15 Stained soil under PW flow line at the east shop wall

Photo 16 trash

Inspection Photos
Location Name: Andrews (Lanyard Water Flood) 23-18
Location ID: 317994



Photo 17 trash

Photo 18 trash