

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/06/2022

Submitted Date:

05/10/2022

Document Number:

699603061

**FIELD INSPECTION FORM**Loc ID 332267 Inspector Name: Evins, Bret On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 10071

Name of Operator: HIGHPOINT OPERATING CORPORATION

Address: 555 17TH ST STE 3700

City: DENVER State: CO Zip: 80202

**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

8 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone | Email                         | Comment         |
|--------------|-------|-------------------------------|-----------------|
| ,            |       | Inspections@civiresources.com | All Inspections |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name  | Insp Status |
|-------------|------|--------|-------------|------------|-----------|----------------|-------------|
| 271459      | WELL | TA     | 08/01/2021  | GW         | 123-22062 | SIEBRING 31-32 | TA          |

**General Comment:**

This is a WELL inspection.

Well(s): 1: Temporarily Abandoned | TA.

Battery: Inactive | Shut-down.

Centralized Battery serves 1 Tank Battery Facility ID (430337).

Centralized Battery serves 5 Location IDs (306088, 332148, 332236, 332237, 332267).

(Well(s): 5: Temporarily Abandoned | TA).

Refer to Field Inspection Report doc. #699603051 and/or Facility ID #430337 for Battery / Facility, Equipment info.

**Location**

|                    |          |       |  |
|--------------------|----------|-------|--|
| <b>Lease Road:</b> |          |       |  |
| Type               | Access   |       |  |
| comment:           | Adequate |       |  |
| Corrective Action  | L        | Date: |  |

Overall Good: ☐

|                      |          |       |  |
|----------------------|----------|-------|--|
| <b>Signs/Marker:</b> |          |       |  |
| Type                 | WELLHEAD |       |  |
| Comment:             |          |       |  |
| Corrective Action:   |          | Date: |  |

|                           |  |             |
|---------------------------|--|-------------|
| Emergency Contact Number: |  |             |
| Comment:                  |  |             |
| Corrective Action:        |  | Date: _____ |

Overall Good: ☐

|                |      |        |  |
|----------------|------|--------|--|
| <b>Spills:</b> |      |        |  |
| Type           | Area | Volume |  |

In Containment: No

Comment: ☐ Multiple Spills and Releases?

|                    |             |       |  |
|--------------------|-------------|-------|--|
| <b>Fencing/:</b>   |             |       |  |
| Type               | WELLHEAD    |       |  |
| Comment:           | Iron panel. |       |  |
| Corrective Action: |             | Date: |  |

|                    |                             |       |                 |
|--------------------|-----------------------------|-------|-----------------|
| <b>Equipment:</b>  |                             |       | corrective date |
| Type: Plunger Lift | # 1                         |       |                 |
| Comment:           |                             |       |                 |
| Corrective Action: |                             | Date: |                 |
| Type: Bradenhead   | # 1                         |       |                 |
| Comment:           | Appears plumbed to surface. |       |                 |
| Corrective Action: |                             | Date: |                 |

**Tanks and Berms:**

| Contents           | #  | Capacity | Type                | Tank ID | SE GPS                |
|--------------------|--|----------|---------------------|---------|-----------------------|
|                    |  |          | CENTRALIZED BATTERY |         | 40.363010,-104.450910 |
| Comment:           | Centralized Battery serves 1 Tank Battery Facility ID (430337).<br>Centralized Battery serves 5 Location IDs (306088, 332148, 332236, 332237, 332267).<br>(Well(s): 5: Temporarily Abandoned   TA).<br><br>Refer to Field Inspection Report doc. #699603051 and/or Facility ID #430337 for Battery / Facility, Equipment info. |          |                     |         |                       |
| Corrective Action: |  |          |                     |         | Date:                 |

**Paint**

|                  |  |  |
|------------------|--|--|
| Condition        |  |  |
| Other (Content)  |  |  |
| Other (Capacity) |  |  |
| Other (Type)     |  |  |

**Berms**

|                    |          |                     |                     |             |
|--------------------|----------|---------------------|---------------------|-------------|
| Type               | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|                    |          |                     |                     |             |
| Comment:           |          |                     |                     |             |
| Corrective Action: |          |                     |                     | Date:       |

**Venting:**

|                    |    |       |  |
|--------------------|----|-------|--|
| Yes/No             | NO |       |  |
| Comment:           |    |       |  |
| Corrective Action: |    | Date: |  |

**Flaring:**

|                    |  |       |
|--------------------|--|-------|
| Type               |  |       |
| Comment:           |  |       |
| Corrective Action: |  | Date: |

**Inspected Facilities**Facility ID: 271459 Type: WELL API Number: 123-22062 Status: TA Insp. Status: TA**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: EQUIPMENT PRESENT/DISCONNECTED

Comment: Temporarily Abandoned | TA.  
Has downhole CIBP.  
COGCC records last production: 10/2020.

Form 5A on file. TA date: 09/21/2021. Approval Pending.  
Form 21 MIT on file. MIT date: 09/23/2021. Approved.  
Form 42 Notice-MIT on file. Date: 09/23/2021. Approved.  
Form 42 Notice-MIRU on file. Date: 09/21/2021. Approved.

Corrective Action:  Date: **BradenHead**Date of Last Brhd Test: 01/24/2022 Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: End Surf Csg Pressure: 0Comment: Corrective Action:  Date:

**Reclamation - Storm Water - Pit****Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Gravel           | Pass            |                         |                       |               |                          |         |

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PIT**COGCC Comments**

| Comment  | User   | Date       |
|--|--------|------------|
| <p><b>COGCC Inspection Report Summary:</b></p> <p>On FRI 05/06/2022 at approximately 12:57 hrs. I, Bret Evins, conducted an on-site inspection at:<br/> Operator Name: HIGHPOINT OPERATING CORPORATION<br/> Location Name: SIEBRING-65N63W /32NWNE<br/> Location ID: 332267<br/> Well Name(s):<br/> Siebring 31-32.<br/> API: 05-123-22062.<br/> Location County: Weld County, Colorado<br/> Weather: Partly Sunny w/ haze, damp from prior storm.</p> <p>While there, I observed:<br/> Well(s): 1: Temporarily Abandoned   TA.<br/> Battery: Inactive   Shut-down.</p> <p>Centralized Battery serves 1 Tank Battery Facility ID (430337).<br/> Centralized Battery serves 5 Location IDs (306088, 332148, 332236, 332237, 332267).<br/> (Well(s): 5: Temporarily Abandoned   TA).</p> <p>Refer to Field Inspection Report doc. #699603051 and/or Facility ID #430337 for Battery / Facility, Equipment info.</p> <p>During this inspection, NO possible compliance issues were observed.</p> <p>This is a summary of the inspection report.</p> | evinsb | 05/10/2022 |

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL   |
|--------------|-------------|---|
| 699603062    | Site photos | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5749957">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5749957</a> |