

FORM
INSPRev
X/20

State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/29/2022

Submitted Date:

05/04/2022

Document Number:

702500003

FIELD INSPECTION FORM

Loc ID 326571 Inspector Name: Klink, Alex On-Site Inspection 2A Doc Num: _____

Operator Information:OGCC Operator Number: 10749Name of Operator: SIMCOE LLCAddress: 1199 MAIN AVE SUITE 101City: DURANGO State: CO Zip: 81301**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:15 Number of Comments1 Number of Corrective Actions

-
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

| Contact Name | Phone | Email | Comment |
|------------------|-------|-------------------------------|---------------------------------|
| Labowskie, Steve | | steve.labowskie@state.co.us | |
| Beebe, Sabre | | sbeebe@ikavenergy.com | All Inspections |
| , General | | sjninspections@ikavenergy.com | All Inspections |

General Comment:

[Inspector Alex Klink on site at 14:20 PM to conduct routine inspection.](#)

Location

Overall Good:

| | | | |
|----------------------|---|-------|------------|
| Signs/Marker: | | | |
| Type | TANK LABELS/PLACARDS | | |
| Comment: | Buried produced water tank information placard facing inward (IMG-0013) and partially obstructed by stock panel (IMG-0012). | | |
| Corrective Action: | Install sign to comply with Rule 605.g. | Date: | 06/03/2022 |

| | | |
|---------------------------|----------------------|----------------------------|
| Emergency Contact Number: | | |
| Comment: | <input type="text"/> | |
| Corrective Action: | <input type="text"/> | Date: <input type="text"/> |

Overall Good:

| | | | |
|----------------|------|--------|--|
| Spills: | | | |
| Type | Area | Volume | |

In Containment: No

Comment:

Multiple Spills and Releases?

| | | | |
|--------------------|---|-------|--|
| Fencing/: | | | |
| Type | OTHER | | |
| Comment: | Wellhead, seperators, and produced water tank are fenced with stock panels. | | |
| Corrective Action: | | Date: | |

| Equipment: | | | corrective date |
|---------------------------|---|-------|-----------------|
| Type: Flow Line | # 1 | | |
| Comment: | Line from seperator to meter house. | | |
| Corrective Action: | | Date: | |
| Type: Flow Line | # 1 | | |
| Comment: | Line from wellhead to seperator | | |
| Corrective Action: | | Date: | |
| Type: Other | # | | |
| Comment: | Linear rod pump. | | |
| Corrective Action: | | Date: | |
| Type: Flow Line | # 1 | | |
| Comment: | Line from seperator to produced water tank. | | |
| Corrective Action: | | Date: | |
| Type: Gas Meter Run | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Ancillary equipment | # 1 | | |
| Comment: | Electric meter panel | | |
| Corrective Action: | | Date: | |
| Type: Bradenhead | # 1 | | |

| | | |
|--|-----|-------|
| Comment: Bradenhead is accessible. | | Date: |
| Corrective Action: | | Date: |
| Type: Vertical Heated Separator | # 1 | |
| Comment: | | Date: |
| Corrective Action: | | Date: |
| Type: Bird Protectors | # 1 | |
| Comment: Seperator vent stack screened properly. | | Date: |
| Corrective Action: | | Date: |

Tanks and Berms:

| Contents | # | Capacity | Type | Tank ID | SE GPS |
|---|---|----------|-----------|---------|-----------------------|
| PRODUCED WATER | 1 | <50 BBLs | STEEL AST | | 37.274881,-107.546608 |
| Comment: Partially buried steel produced water tank. Hatch is properly secured closed (IMG-0016). | | | | | |
| Corrective Action: | | | | | Date: |

Paint

| | |
|------------------|----------------|
| Condition | Adequate |
| Other (Content) | Produced water |
| Other (Capacity) | 21 |
| Other (Type) | Cone top |

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|---|----------|---------------------|---------------------|-------------|
| Metal | Adequate | Walls Sufficient | Base Sufficient | Adequate |
| Comment: Metal berm around partially buried tank. | | | | |
| Corrective Action: | | | | |
| | | Date: | | |

Venting:

| | | |
|--------------------|--|-------|
| Yes/No | | Date: |
| Comment: | | Date: |
| Corrective Action: | | Date: |

Flaring:

| | | |
|--------------------|--|-------|
| Type | | Date: |
| Comment: | | Date: |
| Corrective Action: | | Date: |

Location Construction

Location ID: 258122 CDP: _____

Comment:

Corrective Action:

Date: _____

Form 2A COAs:

Comment:

Corrective Action:

Date: _____

Wildlife BMPs:

Comment:

Corrective Action:

Date: _____

Comment:

Corrective Action:

Date: _____

On Site Inspection (305):

Surface Owner Contact Information:

Name: _____ Address: _____

Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____

Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|-------------------------|---|
| 403038197 | INSPECTION SUBMITTED | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5744416 |
| 702500026 | Image doc | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5744406 |