

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
403032645

Date Received:
04/29/2022

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

1 of 3 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10456

Name of Operator: CAERUS PICEANCE LLC

Address: 1001 17TH STREET #1600

City: DENVER State: CO Zip: 80202

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Romana Cowden

720-951-5895

cogcc.inspections@carusoilandgas.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 702800145

Inspection Date: 04/21/2022

FIR Submit Date: 04/22/2022

FIR Status: _____

Inspected Operator Information:

Company Name: CAERUS PICEANCE LLC

Company Number: 10456

Address: 1001 17TH STREET #1600

City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 334853

Location Name: SHIDELER-66S92W Number: 32SWNE County: _____

Qtrqr: SWNE Sec: 32 Twp: 6S Range: 92W Meridian: 6

Latitude: 39.485530 Longitude: -107.688640

FACILITY - API Number: 05-045- -00 Facility ID: 334853

Facility Name: SHIDELER-66S92W Number: 32SWNE

Qtrqr: SWNE Sec: 32 Twp: 6S Range: 92W Meridian: 6

Latitude: 39.485530 Longitude: -107.688640

CORRECTIVE ACTIONS:

1 ☒ CA# 161251

Corrective Action: Assess the integrity of the secondary metal containment and liner demonstrating that both the metal containment and the liner are compliant with Rule 603.o. Provide results and findings on a FIRR.

Date: 04/25/2022

Comply with Rules 902.a. and 912.d.(3) providing results and findings on either a Form 19 to area EPS if applicable or on a FIRR if a Form 19 is not applicable.

Response: CA COMPLETED

Date of Completion: 04/21/2022

Rule 603.o. only applies to new and significantly modified Tanks. If the secondary containment is replaced Caerus will comply with all COGCC regulations. Per Rule 902.a. and 912.d Caerus has inspected the location and has not identified a current or historic spill within or around the secondary containment of this location.

Operator Comment: Caerus believes the salt identified on the pad location is the result of background mineral deposits similar to what has been observed immediately off location. Caerus will continue to monitor the site for future changes.

COGCC Decision: **Not Approved**

COGCC Representative: During the field inspection #702800145 on 4/21/22, no other salt staining of this nature was observed on Location. Additionally, it can be observed from the inspection photo that the ground along the secondary containment ring is sloped slightly upwards towards the edge of the secondary containment ring. Given these site characteristics, stormwater would not be expected to accumulate at that location and leave background mineral deposits after evaporation, as might be expected in the area. Caerus should assess the integrity of the secondary metal containments ring and liner to ensure they are not compromised. This can be accomplished by pulling back the pea gravel in this area and inspecting the integrity of the liner.

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Romana Cowden

Signed:

Title: EHS

Date: 4/29/2022 10:51:10 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

Document Number **Description**

403032645	FIR RESOLUTION SUBMITTED
-----------	--------------------------

Total Attach: 1 Files