

FORM
INSPRev
X/20State of Colorado
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/10/2022

Submitted Date:

05/11/2022

Document Number:

702800196

FIELD INSPECTION FORM

 Loc ID 313364 Inspector Name: O'Malley, Anna On-Site Inspection 2A Doc Num: _____
Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:7 Number of Comments1 Number of Corrective Actions

-
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**Operator Information:**OGCC Operator Number: 10759Name of Operator: ORGANIC ENERGY COMPANY LLCAddress: 1318 SMEDE HWY (HWY 92)City: BROUSSARD State: LA Zip: 70518**Contact Information:**

Contact Name	Phone	Email	Comment
Bienvenu, Ben	281-300-5049	ben@organicenergyco.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
313364	LOCATION	AC			-	ALLEN-66N91W 8SESE	RI

General Comment:

On 05/10/2022, Reclamation Specialist O'Malley conducted a reclamation and stormwater inspection at Organic Energy Company LLC's Allen-66N91W /8SESE Location #313364 in Moffat County, Colorado.

The following compliance issues were observed during this inspection:

- Noxious Weeds: toadflax, knapweed, thistle

Refer to the "Location," "Reclamation," and "Stormwater" sections of this inspection report for additional details.

Refer to the photo-documentation of the observed compliance issues attached to this report.

Any corrective action(s) from previous inspections that have not been addressed are still applicable.

A follow up inspection on this site will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

Location

Overall Good:

Signs/Marker:

Type	BATTERY		
Comment:	Previous inspection #689805687 observed tank battery sign incomplete. Inspector required Operator to Install sign to comply with Rule 605.e by 7/5/21. It was observed in this inspection that a sign is present at the tank battery which complies with Rule 605.e. It appears this corrective action has been addressed.		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Previous inspection #689805687 observed sign not posted or information inaccurate at well(s). Inspector required Operator to Install sign to comply with Rule 605.d by 7/5/21. It was observed in this inspection that a sign is present at the well which complies with Rule 605.d. It appears this corrective action has been addressed.		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 313364 Type: LOCATION API Number: - Status: AC Insp. Status: RI

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1002 SITE PREPARATION AND STABILIZATION

1002a. FENCING _____

Comment _____

Corrective Action _____

Date _____

1002b. SOIL REMOVAL AND _____

Comment _____

Corrective Action _____

Date _____

1002c. PROTECTION OF SOILS In Process

Comment [A soil stockpile at the south of the Location is colonized by a variety of perennial grasses and is stable at the time of this inspection. However, it is also colonized by a variety of weeds, some noxious. Refer to weed management corrective action under "Interim Reclamation."](#)

Corrective Action _____

Date _____

1002E. SURFACE DISTURBANCE MINIMIZATION _____

Comment _____

Corrective Action _____

Date _____

1003a. Waste and Debris removed? _____

Comment _____

Corrective Action _____

Date _____

Unused or unneeded equipment onsite? _____

Comment _____

Corrective Action _____

Date _____

Pit, cellars, rat holes and other bores closed? _____

Comment _____

Corrective Action _____

Date _____

Guy line anchors marked? _____

Comment _____

Corrective Action _____

Date _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

Comment: _____

Corrective Action: _____

Date _____

Overall Final Reclamation _____

Well Release on Active Location

Multi-Well Location

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: At the time of this inspection, no stormwater issues were observed and the Location is well stabilized by perennial grasses.

Corrective Action: _____

Date: _____

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
Interim Reclamation Comment #1	omalleya	05/11/2022
It was observed in this inspection the the working pad area has been reduced and interim reclamation has been performed in areas throughout the Location. Interim areas have not been regraded to match the contour of the surrounding landscape. Some areas appear to still contain gravel. At the time of this inspection interim area vegetation consists of a variety of desirable perennial grasses including western wheatgrass, indian ricegrass, sandberg bluegrass (native) and crested wheatgrass and thinopyrum (introduced). A variety of native forbs are also present along with alfalfa, which is found in the adjacent reference cropland.		

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
702800197	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5751469