

Inspection Photos

API: 055-06219

Operator: PETROGLYPH OPERATING CO

Inspection Date: 5/11/2022



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06219 | Date: 5/11/2022

Inspection Photos



Photo 1. Facing southeast along the access road. There are noxious weeds along the road (Diffuse knapweed).



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06219 | Date: 5/11/2022

Inspection Photos



Photo 2. Facing southeast along the access road. The rock check dams along the road side appear to be controlling erosion.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06219 | Date: 5/11/2022

Inspection Photos



Photo 3. Facing southeast further along the access road. There is erosion occurring along the road that has not been repaired. Previous corrective action not completed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06219 | Date: 5/11/2022

Inspection Photos



Photo 4. Facing east toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06219 | Date: 5/11/2022

Inspection Photos



Photo 5. Facing toward the fill slope. There is sparse vegetation along the fill slope and the plastic netting still remains.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06219 | Date: 5/11/2022

Inspection Photos




Photo 6. There are noxious weeds (Diffuse knapweed) sprouting up near the fill slope.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06219 | Date: 5/11/2022

Inspection Photos



Photo 7. Facing toward the east side of the location. The vegetation is well established at the eastern portion of the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06219 | Date: 5/11/2022