

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type WELLHEAD

Comment: Red AG fencing around wellhead

Corrective Action:

Date: _____

Equipment:

corrective date

Type: Emission Control Device # 1

Comment:

Corrective Action:

Date: _____

Type: Horizontal Heated Separator # 1

Comment:

Corrective Action:

Date: _____

Type: Bradenhead # 1

Comment: plumbed to surface

Corrective Action:

Date: _____

Type: Plunger Lift # 1

Comment:

Corrective Action:

Date: _____

Type: Ancillary equipment # 1

Comment: plunger automation

Corrective Action:

Date: _____

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<100 BBLS	BV CONCRETE		,

Comment:

Corrective Action:

Date: _____

Paint

Condition

Other (Content)

Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance

Comment: shares containment with oil tank	
Corrective Action:	Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLs	STEEL AST		

Comment:	
Corrective Action:	Date:

Paint

Condition	Adequate	
-----------	----------	--

Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate

Comment:	
Corrective Action:	Date:

Venting:

Yes/No	YES		
Comment:	Venting/flaring issue may be present on this site. COGCC data shows that KPK produced, and used same amount of gas since 12/1/18, SI. From 7/1/18 to 11/1/18, previous gas production was several times more than what was used from 2018 to present. Flare sundry notices were denied for this site. Well has been shut in since 1/1/22 according to COGCC data. There is no gas measurement equipment on location, and no gas meter run as this well was part of the third creek pipeline shut down.		
Corrective Action:	Venting/flaring issue may be present on this site. COGCC data shows that KPK produced, and used same amount of gas since 12/1/18, SI. From 7/1/18 to 11/1/18, previous gas production was several times more than what was used from 2018 to present. Flare sundry notices were denied for this site. Well has been shut in since 1/1/22 according to COGCC data. There is no gas measurement equipment on location, and no gas meter run as this well was part of the third creek pipeline shut down.		Date: <u>05/12/2022</u>

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities

Facility ID: 203809 Type: WELL API Number: 001-09369 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: SI

Corrective Action: _____ Date: _____

BradenHead

Date of Last Brhd Test: 03/28/2022 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____

End Surf Csg Pressure: 0

Comment: _____

Corrective Action: _____ Date: _____

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary On 5/9/22 I, Inspector Justin Medina conducted an on-site inspection at: Well Name- Boxelder 22-28 Company Name- KPK API- 05-001-09369 In Adams County Colorado. While there, I observed SI well During this inspection the following possible compliance issues were observed: Venting/flaring issue may be present on this site. COGCC data shows that KPK produced, and used same amount of gas since 12/1/18, SI. From 7/1/18 to 11/1/18, previous gas production was several times more than what was used from 2018 to present. Flare sundry notices were denied for this site. Well has been shut in since 1/1/22 according to COGCC data. There is no gas measurement equipment on location, and no gas meter run as this well was part of the third creek pipeline shut down. Comply with COGCC venting/flaring rules. 5/12/22 A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This inspection does not nullify any orders or NOAV from the COGCC. This is a summary of inspection report.</p>	medinaj	05/12/2022

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699503935	inspection pictures	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5752923