

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/12/2022

Submitted Date:

05/12/2022

Document Number:

699503950

FIELD INSPECTION FORM

Loc ID _____ Inspector Name: MEDINA, JUSTIN On-Site Inspection 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 74165
Name of Operator: RENEGADE OIL & GAS COMPANY LLC
Address: 6155 S MAIN STREET #225
City: AURORA State: CO Zip: 80016

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

6 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Ingvie, Ed	(303) 680-4725	ed@renegadeoilandgas.com	All Inspections
Espinosa, Bill		billespinosa30@yahoo.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
202823	WELL	SI	06/01/2018	OW	001-08228	CHAMPLIN 75 AMOCO 'K' 2	SI

General Comment:

(This area is currently blank for general comments.)

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

Type	#	Comment	Corrective Action	Date	corrective date
Ancillary equipment	# 1	plunger automation			
Plunger Lift	# 1				
Bird Protectors	# 1				
Bradenhead	# 1	plumbed to surface			
Horizontal Heated Separator	# 1				

Tanks and Birms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	100 BBLs	PBV FIBERGLASS		
Comment:	<input type="text"/>				
Corrective Action:	<input type="text"/>				Date: <input type="text"/>

Paint

Condition	Adequate		
Other (Content)	<input type="text"/>		
Other (Capacity)	<input type="text"/>		
Other (Type)	<input type="text"/>		

Birms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance

Comment:		shares containment with oil tank				Date:	
Corrective Action:						Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS		
CRUDE OIL	1	300 BBLs	STEEL AST				
Comment:						Date:	
Corrective Action:						Date:	
Paint							
Condition	Adequate						
Other (Content)							
Other (Capacity)							
Other (Type)							
Berms							
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance			
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate			
Comment:						Date:	
Corrective Action:						Date:	
Venting:							
Yes/No	NO						
Comment:						Date:	
Corrective Action:						Date:	
Flaring:							
Type							
Comment:						Date:	
Corrective Action:						Date:	

Inspected Facilities

Facility ID: 202823 Type: WELL API Number: 001-08228 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: SI

Corrective Action: _____ Date: _____

BradenHead

Date of Last Brhd Test: 12/29/2021 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 2 Fluid Type: NONE

End Surf Csg Pressure: 0

Comment: _____

Corrective Action: _____ Date: _____

COGCC Comments

Comment	User	Date
At time of inspection location appears to be in compliance with COGCC rules. At time of inspection weather conditions were warm, windy, overcast.	medinaj	05/12/2022

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699503951	inspection photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5752931