

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/12/2022

Submitted Date:

05/13/2022

Document Number:

690103016

FIELD INSPECTION FORMLoc ID 332539 Inspector Name: Maclaren, Joe On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 69175

Name of Operator: PDC ENERGY INC

Address: 1775 SHERMAN STREET - STE 3000

City: DENVER State: CO Zip: 80203

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

3 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
		cogccinspection@pdce.com	
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
243634	WELL	TA	06/01/2020	OW	123-11426	WIEDEMAN 21-1	PA
464927	Location	AC			-	WIEDEMAN-65N67W 21NWSW	EG
482136	SPILL OR RELEASE	AC			-	Weideman 21-1 Sep.	EG

General Comment:COGCC Engineering Integrity Inspection; Flowline Inspection
Photos uploaded

Inspected Facilities

Facility ID: 243634 Type: WELL API Number: 123-11426 Status: TA Insp. Status: PA

Flowline

#1	Type: Non-Well Site	of Lines
----	---------------------	----------

Flowline Description

Flowline Type: Non-Well Site Size: Material:
 Variance: Age: Contents:

Integrity Summary

Failures: Spills: Repairs Made:
 Coatings: H2S: Cathodic Protection:

Pressure Testing

Witnessed: Test Result: Charted:

COGCC Rules(check all that apply)

☐ 1101. Installation and Reclamation ☐ 1102. Operations, Maintenance, and Repair ☒ 1103. Abandonment

Comment: Well (Wiedeman 21-1) has been plugged and abandoned; Cut and cap work is completed. COGCC form 42 notice of start of plugging operations doc #402921141 received 01/09/2022. COGCC form 42 flowline pre-abandonment notice doc #402891597 received on 12/07/2021. Wellhead flowline (OLF) was approx 500' in length; flowline has been AIP/ removed.No flowline risers were observed at the (PA) wellheads or facility/ battery areas during this field inspection. Facility/ battery has been decommissioned; tanks, equipment and dump/ process flowlines removed.

Corrective Action:

Date:

Facility ID: 464927 Type: Location API Number: - Status: AC Insp. Status: EG

Facility ID: 482136 Type: SPILL OR API Number: - Status: AC Insp. Status: EG

COGCC Comments

Comment	User	Date
As outlined on COGCC form 19 spill report Doc #403042382 received on 05/09/2022: PDC discovered a reportable release at the Wiedeman 21-1 around the flowline between the separator and wellhead. Release clean-up and delineation activities are underway.	maclarej	05/13/2022

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
690103022	Location photo; view N	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5753809
690103023	PA well; No flowline risers	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5753810