

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/12/2022

Submitted Date:

05/13/2022

Document Number:

700704190

**FIELD INSPECTION FORM**Loc ID 323818 Inspector Name: Ramsey, Scott On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 10550

Name of Operator: MUSTANG RESOURCES LLC

Address: 1660 LINCOLN STREET SUITE 1450

City: DENVER State: CO Zip: 80264

**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

5 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone        | Email                           | Comment            |
|--------------|--------------|---------------------------------|--------------------|
| , Mustang    |              | bcoutts@mustangresourcesllc.com |                    |
| , mustang    | 303-807-5112 | dlemon@mustangresourcesllc.com  | regulatory manager |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name        | Insp Status |
|-------------|------|--------|-------------|------------|-----------|----------------------|-------------|
| 210875      | WELL | PR     | 12/01/2016  | GW         | 045-06633 | DOWNING 24-22-6S-94W | PR          |

**General Comment:****COGCC Inspection Report Summary**

On Thursday 5/12/2022 at approximately 1200, I, Inspector Scott Ramsey, conducted a routine inspection at Mustang Downing 24-22, at Location # 323818 in Garfield county Colorado.

Any Corrective Actions from previous Inspections that have not been addressed are still applicable.

While there, I observed normal production operations. All meters have been calibrated on location within the past year. This location is within or in close proximity to a CPW Density/High Priority Habitat, black bear, NSO habitat, Wildlife Management.

During this inspection the following possible compliance issues were observed:

1. Some areas of location show signs of lack of stabilization/ compaction/ degradation/ erosion.

Refer to photograph of observed compliance issue.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

This is a summary of inspection report.

**Location****Lease Road:**

|                   |        |       |  |
|-------------------|--------|-------|--|
| Type              | Access |       |  |
| comment:          |        |       |  |
| Corrective Action |        | Date: |  |

Overall Good: ☐**Signs/Marker:**

|                    |          |       |  |
|--------------------|----------|-------|--|
| Type               | WELLHEAD |       |  |
| Comment:           |          |       |  |
| Corrective Action: |          | Date: |  |

**Emergency Contact Number:**

|                    |     |       |  |
|--------------------|-----|-------|--|
| Comment:           | 911 |       |  |
| Corrective Action: |     | Date: |  |

**Good Housekeeping:**

|                    |        |       |  |
|--------------------|--------|-------|--|
| Type               | DEBRIS |       |  |
| Comment:           |        |       |  |
| Corrective Action: |        | Date: |  |

Overall Good: ☒**Spills:**

|      |      |        |  |  |
|------|------|--------|--|--|
| Type | Area | Volume |  |  |
|------|------|--------|--|--|

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Equipment:**

|                     |     |       |                 |
|---------------------|-----|-------|-----------------|
| Type: Bradenhead    | # 1 |       | corrective date |
| Comment:            |     |       |                 |
| Corrective Action:  |     | Date: |                 |
| Type: Gas Meter Run | # 1 |       |                 |
| Comment:            |     |       |                 |
| Corrective Action:  |     | Date: |                 |
| Type: Plunger Lift  | # 1 |       |                 |
| Comment:            |     |       |                 |
| Corrective Action:  |     | Date: |                 |

**Venting:**

|                    |    |       |  |
|--------------------|----|-------|--|
| Yes/No             | NO |       |  |
| Comment:           |    |       |  |
| Corrective Action: |    | Date: |  |

**Flaring:**

|      |  |  |
|------|--|--|
| Type |  |  |
|------|--|--|

|                    |  |       |  |
|--------------------|--|-------|--|
| Comment:           |  |       |  |
| Corrective Action: |  | Date: |  |

| Inspected Facilities |           |       |      |             |           |         |    |               |    |
|----------------------|-----------|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID:         | 210875    | Type: | WELL | API Number: | 045-06633 | Status: | PR | Insp. Status: | PR |
| Producing Well       |           |       |      |             |           |         |    |               |    |
| Comment:             | Producing |       |      |             |           |         |    |               |    |
| Corrective Action:   |           |       |      | Date:       |           |         |    |               |    |

**Reclamation - Storm Water - Pit****Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Compaction       | Fail            |                         |                       |               |                          |         |

Comment: 1. Some areas of location show signs of lack of stabilization/ compaction/ degradation/ erosion.

Corrective Action: Install or repair required BMPs

Date: 06/24/2022

**Pits:** ☒ NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL   |
|--------------|-------------|---|
| 700704200    | Photo log   | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5753833">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5753833</a> |