

FORM
INSPRev
X/20State of Colorado
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/12/2022

Submitted Date:

05/13/2022

Document Number:

700704192

FIELD INSPECTION FORM

 Loc ID 335511 Inspector Name: Ramsey, Scott On-Site Inspection 2A Doc Num:

Operator Information:

OGCC Operator Number: 96850

Name of Operator: TEP ROCKY MOUNTAIN LLC

Address: 1058 COUNTY ROAD 215

City: PARACHUTE State: CO Zip: 81635

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 11 Number of Comments
- 2 Number of Corrective Actions

 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
, TEP	970-285-9377	COGCCInspectionReports@terraep.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
300395	WELL	PR	06/01/2011	GW	045-17901	DOWNING RWF 522-24	PR
300396	WELL	PR	06/30/2010	GW	045-17902	DOWNING RWF 22-24	PR
300397	WELL	PR	06/30/2010	GW	045-17903	DOWNING RWF 511-24	PR
300398	WELL	PR	06/30/2010	GW	045-17904	DOWNING RWF 311-24	PR

General Comment:

COGCC Inspection Report Summary

On Thursday 5/12/2022 at approximately 1000, I, Inspector Scott Ramsey, conducted a routine inspection at TEP RWF 22-24, at Location # 335511 in Garfield county Colorado.

Any Corrective Actions from previous Inspections that have not been addressed are still applicable.

While there, I observed normal production operations. All meters have been calibrated on location within the past year. This location is within or in close proximity to a CPW Density/High Priority Habitat, black bear, NSO habitat, Wildlife Management. Operator (TERRA) has provided there Piceance Basin Storm water Manual of BMP's (SC-4) for a tracking pad.

During this inspection the following possible compliance issues were observed:

1. Some areas of access show signs of lack of stabilization/ compaction/ degradation.
2. Valve on tank missing cap/plug.
3. Rat holes at well heads subsidence.

Refer to photograph of observed compliance issue.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

This is a summary of inspection report.

Location			
Lease Road:			
Type	Access		
comment:	See stormwater		
Corrective Action			Date:
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
Type	BATTERY		
Comment:			
Corrective Action:			Date:
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:			Date:
Type	OTHER		
Comment:	Separator units include attached storage tanks. The sight glass located on the side of the unit indicates the storage tank is full of an unknown fluid. No form of labeling or markers are present to identify a potential hazard or the contents of the storage tank.		
Corrective Action:			Date:
Type	CONTAINERS		
Comment:			
Corrective Action:			Date:
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	911		
Corrective Action:			Date: _____
Good Housekeeping:			
Type	OTHER		
Comment:	Valve on tank missing cap/plug.		
Corrective Action:	Install cap/bull plug		Date: 06/03/2022
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No _____			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	TANK BATTERY		
Comment:			

Corrective Action:		Date:	
Type	SEPARATOR		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Equipment:			corrective date
Type: Plunger Lift	# 4		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 4		
Comment:			
Corrective Action:		Date:	
Type: Pig Station	# 1		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Chemical tank in plastic containment		
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 4		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 2		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	300 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate	
Comment:					
Corrective Action:					Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	2	300 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate	
Comment:					
Corrective Action:					Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			
		Date:	

Flaring:

Type	
Comment:	
Corrective Action:	
	Date:

Inspected Facilities									
Facility ID:	<u>300395</u>	Type:	<u>WELL</u>	API Number:	<u>045-17901</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
<u>Producing Well</u>									
Comment:	<u>Producing</u>								
Corrective Action:					Date:				
Facility ID:	<u>300396</u>	Type:	<u>WELL</u>	API Number:	<u>045-17902</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
<u>Producing Well</u>									
Comment:	<u>Producing</u>								
Corrective Action:					Date:				
Facility ID:	<u>300397</u>	Type:	<u>WELL</u>	API Number:	<u>045-17903</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
<u>Producing Well</u>									
Comment:	<u>Producing</u>								
Corrective Action:					Date:				
Facility ID:	<u>300398</u>	Type:	<u>WELL</u>	API Number:	<u>045-17904</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
<u>Producing Well</u>									
Comment:	<u>Producing</u>								
Corrective Action:					Date:				

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Fail					
		Compaction	Fail			

Comment: [1. Some areas of access and location show signs of lack of stabilization/ compaction/ degradation.](#)
[2. Rat holes at well heads subsidence.](#)

Corrective Action: [Install or repair required BMPs](#)

Date: 06/24/2022

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
700704202	Photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5753835