

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/16/2022

Submitted Date:

05/16/2022

Document Number:

687400863

FIELD INSPECTION FORMLoc ID 320439 Inspector Name: Huck, Keith On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 74165

Name of Operator: RENEGADE OIL & GAS COMPANY LLC

Address: 6155 S MAIN STREET #225

City: AURORA State: CO Zip: 80016

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

17 Number of Comments

4 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Pesicka, Conor		conor.pesicka@state.co.us	
Ingvie, Ed	(303) 680-4725	ed@renegadeoilandgas.com	All Inspections
Espinosa, Bill		billespinosa30@yahoo.com	Inspections
, COGCC		mike.leonard@state.co.us	
Gomez, Jason		jason.gomez@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
203756	WELL	PR	09/01/2021	OW	001-09316	HOSMER 4-6	PR

General Comment:

Location

Overall Good: ☒

Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:	Adequate		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	
Type	BATTERY		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:	
Comment:	Adequate
Corrective Action:	
	Date: _____

Good Housekeeping:			
Type	OTHER		
Comment:	Control and contain spills/releases and clean up per Rule 912.a. See attached pictures 12&13		
Corrective Action:	30-days to clean up and remove stained soil.	Date:	06/17/2022

Overall Good: ☐

Spills:				
Type	Area	Volume		
In Containment: No				
Comment:				
<input type="checkbox"/> Multiple Spills and Releases?				

Fencing/:			
Type	TANK BATTERY		
Comment:	4 strand barbed wire		
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	4 strand barbed wire		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	4 strand barbed wire		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Pump Jack	# 1		
Comment:			

Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	Appears to be plumbed to surface		
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	
Type: Other	# 2		
Comment:	(1) Bitcoin mining building (1) Bitcoin mining trailer		
Corrective Action:		Date:	
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 3		
Comment:	Natural gas generators		
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER		100 BBLs	FIBERGLASS AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				

Inspector Name: Huck, Keith

Corrective Action:					Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS	
CRUDE OIL	2	300 BBLs	STEEL AST		39.907247,-104.557341	
Comment:					Loadlines. All loadlines will be bullplugged or capped. See attached picture 3	
Corrective Action:					Date: 05/23/2022	

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Wells Served By Facilities Above

AirsID

API Number	API Number	AirsID
001-09316		

Venting:

Yes/No	YES	
Comment:	Venting gas out the top of produced water tank. See attached video	
Corrective Action:	Immediately cease venting/flaring. Submit Form 4 for review and approval to vent or flare.	Date: 05/17/2022

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities

Facility ID: 203756 Type: WELL API Number: 001-09316 Status: PR Insp. Status: PR

Producing Well

Comment: Appears to be using gas from the well to power the generators on location. Which appear to be powering the BitCoin operations on site.

Corrective Action: Submitt gas capture plane to COGCC with in 5 days of recieving this inspection

Date: 05/23/2022

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On (Thursday) (05/13/2022) at approximately (09:25am), I, Inspector (Keith Huck), conducted an on-site inspection at (Wenzel Hosmer 4-4) (KPK), at (Location#319871) in (Adams,County) Colorado.</p> <p>While there, I observed a Production Facility with BitCoin operations on site and running. Control and contain spills/releases and clean up per Rule 912.a.</p> <p>See attached pictures 12&13</p> <p>Corrective action date: 6/17/2022</p> <p>Load lines. All load lines will be bull plugged or capped. See attached picture 3</p> <p>Corrective Action Date:5/23/2022</p> <p>Appears to be using gas from the well to power the generators on location. Which appear to be powering the Bit Coin operations on site.</p> <p>Corrective Action Date:5/23/2022</p> <p>Submit gas capture plane to COGCC within 5 days of receiving this inspection</p> <p>Venting gas out the top of produced water tank.</p> <p>See attached video.</p> <p>Immediately cease venting/flaring. Submit Form 4 for review and approval to vent or flare.</p> <p>Submit gas capture plane to COGCC within 5 days of receiving this inspection</p> <p>A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of inspection report.</p>	huckk	05/16/2022

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
687400864	Hosmer4-6Venting From Produced Water Tank	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5755138
687400865	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5755139