

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/16/2022

Submitted Date:

05/17/2022

Document Number:

696203700

FIELD INSPECTION FORM

Loc ID 335594 Inspector Name: Trujillo, Aaron On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10456
Name of Operator: CAERUS PICEANCE LLC
Address: 1001 17TH STREET #1600
City: DENVER State: CO Zip: 80202

Findings:

- 3 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
,		COGCC.inspections@caerusoilandgas.com	
		steven.kirschner@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
335594	LOCATION	AC			-	N.PARACHUTE-65S95W 29SENE	RI

General Comment:

On 5/16/2022, Reclamation Specialist Trujillo conducted a stormwater inspection at Caerus Piceance's N. Parachute-65S95W 29SENE (H29A) location in Garfield County, Colorado.

This inspection is a followup to No. 696202450 dated 3/9/2021, and No. 696203600 dated 4/22/2022 to document compliance with the following corrective actions:

-1002.f Stormwater

It was observed in this inspection that the Location remains out of compliance with COGCC Rules and corrective actions.

The following new compliance issues were observed during this inspection:

- 606: Debris

Refer to the "Stormwater" and "Good Housekeeping" section of this inspection report for additional details.

Refer to the photo-documentation of the observed compliance issues attached to this report.

Any corrective action(s) from previous inspections that have not been addressed are still applicable.

A follow up inspection on this site will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type

DEBRIS

Comment:

Shrub vegetation appears to have been removed from areas of the Location (including slopes on the north end of the site); vegetation has been piled on the west end of the working pad; this is considered debris and requires removal.

Corrective Action:

Comply with Rule 606

Date:

05/24/2022

Overall Good:

Spills:

Type

Area

Volume

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:

Yes/No

Comment:

Corrective Action:

Date:

Flaring:

Type

Comment:

Corrective Action:

Date:

Inspected Facilities

Facility ID: 335594 Type: LOCATION API Number: - Status: AC Insp. Status: RI

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Previous inspections observed BMPs at slopes on the north end of the Location were missing or insufficient. Inspections required Operator to comply with Rule 1002.f by 5/6/2022.

It was observed in this inspection that control measures to minimize erosion, degradation, and to stabilize the slopes on the north end of the Location are missing or insufficient; inspection #696203600 observed control measures (hydromulch) in disrepair; hydromulch no longer evident; no additional controls appear to have been implemented; erosion degradation and stabilization issues at the slopes have persisted.

Corrective Action: **Install or repair required BMPs per Rule 1002.f.**

Date: 05/06/2022

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696203701	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5755558