

**FORM
INSP**Rev
X/20

State of Colorado

Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

05/16/2022

Submitted Date:

05/17/2022

Document Number:

690103024

FIELD INSPECTION FORM
 Loc ID 331480 Inspector Name: Maclaren, Joe On-Site Inspection ☐ 2A Doc Num:
Operator Information:

OGCC Operator Number: 47120

Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP

Address: P O BOX 173779

City: DENVER State: CO Zip: 80217-

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

4 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**
Contact Information:

Contact Name	Phone	Email	Comment
		COGCCInspections@Oxy.com	
Chesson, Robert		robert.chesson@state.co.us	
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
262516	WELL	SI	07/01/2020	GW	123-20751	CANNON 3-3A	PA
450404	LOCATION	AC			-	UPRR 38 PAN AM E 2 BATTERY	EG
482180	SPILL OR RELEASE	CL			-	Cannon 3-3A Wellhead	EG
482181	SPILL OR RELEASE	CL			-	UPRR 38 Pan Am E 2 Battery	EG

General Comment:
 COGCC Engineering Integrity Inspection; Flowline Inspection
 Photos uploaded

Inspected Facilities

Facility ID: 262516 Type: WELL API Number: 123-20751 Status: SI Insp. Status: PA

Flowline

#1	Type: Non-Well Site	of Lines
----	---------------------	----------

Flowline Description

Flowline Type: Non-Well Site Size: 2" Material: Carbon Steel
 Variance: Age: Contents:

Integrity Summary

Failures: Spills: Repairs Made:
 Coatings: H2S: Cathodic Protection:

Pressure Testing

Witnessed: Test Result: Charted:

COGCC Rules (check all that apply)

☐ 1101. Installation and Reclamation ☐ 1102. Operations, Maintenance, and Repair ☒ 1103. Abandonment

Comment: Well (Cannon 3-3A) has been plugged and abandoned; Cut and cap work is completed. COGCC form 42 notice of start of plugging operations doc #402966144 received 02/25/2022. Open excavations were observed at the PA well and inlet to HHS. Flowline abandonment work is in progress; flowline cut ends observed bull plugged/ valved (wrapped/ taped) below grade at wellhead and facility (inlet to HHS). No OOS flowline risers were observed at the (PA) wellhead or facility/ battery (450404) areas during this field inspection. Facility services additional wells; OOSLAT in place at flowline manifold/ HHS. Excavation/ remediation work in response to historical releases in progress.

Corrective Action:

Date:

Facility ID: 450404 Type: LOCATION API Number: - Status: AC Insp. Status: EG

Facility ID: 482180 Type: SPILL OR API Number: - Status: CL Insp. Status: EG

Facility ID: 482181 Type: SPILL OR API Number: - Status: CL Insp. Status: EG

COGCC Comments

Comment	User	Date
As outlined on COGCC form 19 spill report Doc #403043700 received on 05/12/2022: During plugging and abandonment activities at the Cannon 3-3A wellhead, historically impacted soil and groundwater were discovered at the separator inlet at the associated UPRR 38 Pan Am E 2 Facility. The volume of the release is unknown. The wellhead associated with the separator is being abandoned and the flowline status will be changed from active to left in place.	maclarej	05/17/2022
As outlined on COGCC form 19 spill report Doc #403043689 received on 05/12/2022: During plugging and abandonment activities at the Cannon 3-3A wellhead, historically impacted soil was discovered. The volume of the release is unknown. The well is being plugged and abandoned.	maclarej	05/17/2022

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
690103029	Wellhead signage; flowline AIP	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5756164

690103030	Signage and tank battery	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5756165
690103031	Excavation at HHS; flowline AIP	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5756166