

Inspection Photos  
Operator: Enduring  
API: 067-08658  
Date: 5/13/2022



Photo 1. View of the project area from the well pad entrance facing center.



Photo 2. View of the southern fill slope from the southeastern corner facing westward. Slope is largely rock stabilized with western wheatgrass, rubber rabbitbrush, hairy goldenaster, and crested wheatgrass observed.



Photo 3. View of the eastern project area from the southeastern corner facing northward.



Photo 4. View of reference area pinyon and juniper woodland with understory of shrubs such as antelope bitterbrush, lanceleaf buckwheat, banana yucca, purple threeawn, Indian ricegrass, and claret cup.