

Inspection Photos  
Operator: Enduring  
API: 067-07636  
Date: 5/13/2022



Photo 1. View of the project area from the southeastern corner facing center.



Photo 2. View of the northeastern fill slope from the southeastern corner facing northward. Revegetation is progressing with western wheatgrass, smooth brome, and crested wheatgrass.





Photo 3. View of the southern project area from the southeastern corner facing westward.



Photo 4. View of reference area pinyon and juniper woodland with understory of shrubs such as antelope bitterbrush, lanceleaf buckwheat, banana yucca, purple threeawn, Indian ricegrass, and claret cup cactus.