

Inspection Photos  
Operator: Enduring  
API: 067-07650  
Date: 5/13/2022



Photo 1. View of the project area from the well pad entrance facing center.



Photo 2. View of the eastern fill slope from the northeastern corner facing southward. Revegetation is progressing with western wheatgrass, Indian ricegrass, crested wheatgrass, and sand dropseed.



Photo 3. View of hoary cress weeds (approx. 75) along the access road.



Photo 4. View of culvert outlet at access road crossing. Culvert outlet continues to lack stabilization.



Photo 5. View of roadside ditch with rock placement full of sediment. This is not an adequate BMP for this area.



Photo 6. Another view of rocks placed along roadside and continued erosion along roadside.