

Inspection Photos
Operator: Enduring
API: 067-08734
Date: 5/13/2022



Photo 1. View of the project area from the well pad entrance facing center.



Photo 2. View of the southern project area from the southeastern corner facing westward. Revegetation is progressing with crested wheatgrass and western wheatgrass.



Photo 3. View of the eastern project area from the southeastern corner facing northward.



Photo 4. View of the reference area comprised of sagebrush shrubland with purple threeawn, Indian ricegrass, blue grama, and prickly pear in the understory.