

Inspection Photos
Location Name: Carter 21-33
Location ID: 329511



Photo 1 WH sign.

Photo 2 WH

Inspection Photos
Location Name: Carter 21-33
Location ID: 329511



Photo 3 Pump jack.

Photo 4 Ancillary equip.

Inspection Photos
Location Name: Carter 21-33
Location ID: 329511



Photo 5 TB sign.

Photo 6 TB.

Inspection Photos
Location Name: Carter 21-33
Location ID: 329511



Photo 7 Gas Meter Run, No card to indicate calibration status.

Photo 8 HHS.

Inspection Photos
Location Name: Carter 21-33
Location ID: 329511



Photo 9 Flow line manifold.

Photo 10 Stained soil by WH and Pump Jack base.

Inspection Photos
Location Name: Carter 21-33
Location ID: 329511



Photo 11 Stained soil by WH and Pump Jack base.

Photo 12 Stained soil on WH and Pump Jack location.

Inspection Photos
Location Name: Carter 21-33
Location ID: 329511



Photo 13 Stained soil by WH and Pump Jack base.

Photo 14 Stained soil by West Crude tank.

Inspection Photos
Location Name: Carter 21-33
Location ID: 329511



Photo 15 Stained soil by NE crude tank, Possible pin hole leak.