

Inspection Photos

Location Name: MARALEX RESOURCES INC RIFLE-BOULTON-67S91W /23NWNW

Location ID: 322369



Photo #6702 from entrance to location.



Photo #6703 from entrance to location.

Inspection Photos

Location Name: MARALEX RESOURCES INC RIFLE-BOULTON-67S91W /23NWNW

Location ID: 322369



Photo #6704 from entrance to location.



Photo #6708 Information on battery sign inaccurate.

Inspection Photos

Location Name: MARALEX RESOURCES INC RIFLE-BOULTON-67S91W /23NWNW

Location ID: 322369



Photo #6705 No wellhead sign located at the well head.



Photo #6721 Local emergency contact number not posted. Number that is posted is Maralex western slope office number.

Inspection Photos

Location Name: MARALEX RESOURCES INC RIFLE-BOULTON-67S91W /23NWNW

Location ID: 322369



Photo #6714 Multiple trailers parked on location.



Photo #6706 Multiple places with undesirable plant species encroaching on equipment.


Inspection Photos

Location Name: MARALEX RESOURCES INC RIFLE-BOULTON-67S91W /23NWNW

Location ID: 322369



Network time is not synchronize
Local: May 13, 2022 at 12:01:29 PM MD



Network time is not synchronize
Local: May 13, 2022 at 12:09:49 PM MD

Plate Size			Spot Sample		Meter
IN	OUT	DATE	DATE	CAL DATE	
.625	Insp-	10-27-10	No Flow	05-04-11	
0.500	.625	08-15-11	07-01-11	08-15-11	
			08-15-11	10-20-11	
			10-20-11	01-25-12	
.500	Insp-	04-19-12	04-19-12	04-19-12	
			07-24-12	07-24-12	
.500	Insp-	10-22-12		10-22-12	
				02-07-13	
				04-23-13	
1.000 500	INSF	7-18-14	7-18-14	7/18/14	
1.000	0.500	10-22-14		10-22-14	

Photo #67075 Multiple places with undesirable plant species encroaching on equipment.

Photo #6717 Gas meter out of calibration.

Inspection Photos

Location Name: MARALEX RESOURCES INC RIFLE-BOULTON-67S91W /23NWNW

Location ID: 322369



Photo #6718 Flowline improperly abandon.



Photo #6720 Vent pipe on tank open.

Inspection Photos

Location Name: MARALEX RESOURCES INC RIFLE-BOULTON-67S91W /23NWNW

Location ID: 322369



Photo #6709 Loadline open ended.



Photo #6710 Secondary containment is not sufficiently impervious to contain spilled or released materials.

Inspection Photos

Location Name: MARALEX RESOURCES INC RIFLE-BOULTON-67S91W /23NWNW

Location ID: 322369



Photo #6711 Secondary containment is not sufficiently impervious to contain spilled or released materials.




Photo #6712 Secondary containment is not sufficiently impervious to contain spilled or released materials

Inspection Photos

Location Name: MARALEX RESOURCES INC RIFLE-BOULTON-67S91W /23NWNW

Location ID: 322369



Location is approximately 150 yards from East Divide Creek.



Location is approximately 200 yards from the nearest residences.