

Inspection Photos

May 13, 2022

Operator: Beeman Oil & Gas LLC - #7125

Location ID: 429647

Location Name: Bulldog /5-14H-789

Inspection Document #: 702800216

Moffat County, CO

Lot 17 Section 5 T7N R89W

Anna O'Malley
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: Bulldog /5-14H-789
Location ID: 429647



Photo 1. Photo taken from the entrance road shows Location signage with incorrect Operator information.



Photo 2. Photo taken from the wellhead shows signage with incorrect Operator information.

Inspection Photos
Location Name: Bulldog /5-14H-789
Location ID: 429647



Photo 3. Photo taken from the tank battery shows incorrect Operator information on the tanks.



Photo 4. Photo taken from the tank battery shows Location signage is absent.

Inspection Photos
Location Name: Bulldog /5-14H-789
Location ID: 429647



Photo 5. Photo taken from the north of the Location shows a methanol tank secondary containment stock tank lacking wildlife protection BMPs.



Photo 6. Photo taken from the north of the Location adjacent to the compressor shed shows a methanol tank secondary containment stock tank lacking wildlife protection BMPs.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800216

Inspection Photos
Location Name: Bulldog /5-14H-789
Location ID: 429647



Photo 7. Photo taken from the wellhead shows an open casing.



Photo 8. Photo taken from the northwest of the well shows an unmarked anchor.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800216

Inspection Photos
Location Name: Bulldog /5-14H-789
Location ID: 429647



Photo 9. Photo taken from west of the Location shows houndstongue and bull thistle. CO List B Noxious weeds.



Inspection Photos
Location Name: Bulldog /5-14H-789
Location ID: 429647



Photo 10. Photo taken from the south of the Location shows areas requiring interim reclamation.



Photo 11. Photo taken from the northwest of the Location shows areas requiring interim reclamation.



Inspection Photos
Location Name: Bulldog /5-14H-789
Location ID: 429647



Photo 12. Photo taken from the west of the Location shows where a stormwater berm is not properly designed or maintained in proper functioning condition. Stormwater has incised the berm resulting in a large gully.



Photo 13. Refer to Photo 12 comment. Note also the houndstongue, a CO List B Noxious weed.



Inspection Photos
Location Name: Bulldog /5-14H-789
Location ID: 429647



Photo 14. Photo taken from the southwest of the Location shows where a stormwater pipe is not properly designed or maintained in proper functioning condition. Stormwater has incised the berm around the pipe resulting in a large gully.



Photo 15. Photo taken from the southwest of the Location shows where perimeter ditches lead into a discharge pipe. Erosion of the pad in multiple directions leading into the ditch and pipe is evident.



Inspection Photos
Location Name: Bulldog /5-14H-789
Location ID: 429647



Photo 16. Photo taken adjacent from the west of the Location shows where a stormwater ditch is eroding and forming a gully.



Photo 17. Refer to Photo 16 comment.

