

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/16/2022

Submitted Date:

05/18/2022

Document Number:

702500038

**FIELD INSPECTION FORM**

Loc ID 325816 Inspector Name: Klink, Alex On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Operator Information:**

OGCC Operator Number: 10749  
Name of Operator: SIMCOE LLC  
Address: 1199 MAIN AVE SUITE 101  
City: DURANGO State: CO Zip: 81301

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

17 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Labowskie, Steve		steve.labowskie@state.co.us	
General		sjninspections@ikavenergy.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
215420	WELL	PR	12/31/2001	GW	067-07025	STATE COM BZ 1	PR

**General Comment:**

Inspector Alex Klink on site to conduct routine inspection. Any corrective actions from previous inspections are still applicable. See link at end of report for inspection photos.

<b>Location</b>			
Overall Good: <input type="checkbox"/>			
<b>Signs/Marker:</b>			
Type	TANK LABELS/PLACARDS		
Comment:	Produced water tank sign visible and legible (IMG 09).		
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	Emergency contact present at site entrance (IMG 01).		
Corrective Action:			Date: _____
<b>Good Housekeeping:</b>			
Type	DEBRIS		
Comment:	Unused flange and bolts near wellhead (IMG 06).		
Corrective Action:			Date:
Overall Good: <input type="checkbox"/>			
<b>Spills:</b>			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
<b>Fencing/:</b>			
Type	OTHER		
Comment:	Site is enclosed by wire fence and cattle gaurd.		
Corrective Action:			Date:
<b>Equipment:</b>			
Type: Gas Meter Run			# 1
Comment:			
Corrective Action:			Date:
Type: Flow Line			# 1
Comment:			2" line from separator to meter house.
Corrective Action:			Date:
Type: Ancillary equipment			# 1
Comment:			Telemetry
Corrective Action:			Date:
Type: Flow Line			# 1
Comment:			2" line from separator to produced water tank.
Corrective Action:			Date:
Type: Bird Protectors			# 1
Comment:			Separator vent stack is screened properly (IMG 07).
Corrective Action:			Date:

Type: Bradenhead	# 1	
Comment:	Bradenhead is accessible.	
Corrective Action:		Date:
Type: Deadman # & Marked	# 4	
Comment:	3 anchor markers are upright, 1 anchor marker knocked over.	
Corrective Action:		Date:
Type: Vertical Heated Separator	# 1	
Comment:		
Corrective Action:		Date:
Type: Flow Line	# 1	
Comment:	2" line from wellhead to separator.	
Corrective Action:		Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<100 BBLS	PBV STEEL		37.093548,-107.548362
Comment:	Partially buried produced water tank access hatch is screened (IMG 10).				
Corrective Action:					Date:

**Paint**

Condition	Adequate
Other (Content)	Produced water
Other (Capacity)	95 bbls
Other (Type)	Cone Top

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:	Metal tank berm (IMG 08).			
Corrective Action:				Date:

**Venting:**

Yes/No	
Comment:	
Corrective Action:	Date:

**Flaring:**

Type	
Comment:	
Corrective Action:	Date:

**Inspected Facilities**

Facility ID: 215420 Type: WELL API Number: 067-07025 Status: PR Insp. Status: PR

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: [No observed impacts of stormwater. Stormwater control appears sufficient at time of this inspection.](#)

Corrective Action:

Date: \_\_\_\_\_

**Pits:**  NO SURFACE INDICATION OF PIT

**COGCC Comments**

Comment	User	Date
<a href="#">Wildlife BMP's appear sufficient, all openings and vents are properly screened.</a>	klinka	05/16/2022

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
702500041	Photo doc	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5757128">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5757128</a>