

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/29/2022

Submitted Date:

05/18/2022

Document Number:

688312626

**FIELD INSPECTION FORM**

Loc ID 479197 Inspector Name: Sherman, Susan On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 10243  
Name of Operator: GMT EXPLORATION COMPANY LLC  
Address: 1560 BROADWAY STE 2000  
City: DENVER State: CO Zip: 80202

**Findings:**

5 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

| Contact Name       | Phone        | Email                          | Comment         |
|--------------------|--------------|--------------------------------|-----------------|
| Eberhardt, Whitney | 303-586-9289 | w.eberhardt@gmtexploration.com | Principal Agent |
| Cox, BJ            | 303-586-9274 | bjcox@gmtexploration.com       |                 |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name           | Insp Status |
|-------------|------|--------|-------------|------------|-----------|-------------------------|-------------|
| 480083      | WELL | DG     | 04/22/2022  |            | 039-06703 | Redstone 6-65 24-36 1HN | DG          |

**General Comment:**

[BOP Inspection](#)

**Location**

Overall Good:

**Signs/Marker:**

|                    |  |       |  |
|--------------------|--|-------|--|
| Type               | OTHER                                  |       |  |
| Comment:           | locations signs at CR 178 and entrance |       |  |
| Corrective Action: |  | Date: |  |

**Emergency Contact Number:**

Comment:

Corrective Action:  Date: \_\_\_\_\_

Overall Good:

**Spills:**

| Type | Area | Volume |  |  |
|------|------|--------|--|--|
|------|------|--------|--|--|

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

|                    |          |       |  |
|--------------------|----------|-------|--|
| Type               | LOCATION |       |  |
| Comment:           |          |       |  |
| Corrective Action: |          | Date: |  |

**Venting:**

|                    |  |       |  |
|--------------------|--|-------|--|
| Yes/No             |  |       |  |
| Comment:           |  |       |  |
| Corrective Action: |  | Date: |  |

**Flaring:**

|                    |  |       |  |
|--------------------|--|-------|--|
| Type               |  |       |  |
| Comment:           |  |       |  |
| Corrective Action: |  | Date: |  |

**Inspected Facilities**

Facility ID: 480083 Type: WELL API Number: 039-06703 Status: DG Insp. Status: DG

**Well Drilling**

**Rig:** Rig Name: Ensign 161 Pusher/Rig Manager: Arvid  
 Permit Posted: SATISFACTORY Access Sign: SATISFACTORY

**Well Control Equipment:**

Pipe Ram: YES Blind Ram: YES Hydril Type: YES  
 Pressure Test BOP: Pass Test Pressure PSI: \_\_\_\_\_ Safety Plan: \_\_\_\_\_

**Drill Fluids**

**Management:**

Lined Pit: NO Unlined Pit: NO Closed Loop: YES Semi-Closed Loop: NO  
 Multi-Well: YES Disposal Location: commercial

**Comment:** Pathfinder Pressure Testing/Dakota/Charts  
Outside Choke Manifold 250/5000 psi, 5 min/10 min  
Lower Pipe Rams, Manual IBOP, TIW 250/5000 psi, 5 min/10 min  
Upper Pipe Rams, HCR Valve, 1st Kill Valve, Dart Valve 250/5000 psi, 5 min/10 min  
2nd Kill Valve, Manual Choke Valve 250/5000 psi, 5 min/10 min  
Annualar, 250/3500 psi 5 min/10 min  
Accumulator Function Test 1600 psi, 27.17 sec, 925 psi drop  
Blind Rams, Inside Choke Manifold, Kill Check 250/5000 psi, 5 min/10 min  
Surface casing test, 2500 psi for 30 min

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

**Reclamation - Storm Water - Pit**

**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Blankets         | Pass            | Blankets                | Pass                  |               |                          |         |
| Seeding          | Pass            | Seeding                 | Pass                  |               |                          |         |
| Waddles          | Pass            | Waddles                 | Pass                  |               |                          |         |
| Ditches          | Pass            | Ditches                 | Pass                  |               |                          |         |

Comment: [top soil is stockpiled, antelope next to location fence](#)

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description                        | URL   |
|--------------|------------------------------------|---|
| 688312628    | GMT Redstone 6-65 24-36<br>1HN BOP | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5757497">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5757497</a> |