

Inspection Photos

API: 073-06189

Operator: MAGPIE OPERATING INC

Inspection Date: 5/17/2022



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 073-06189 | Date: 5/17/2022

Inspection Photos



Photo 1. Facing south toward the access road. The cattle guard has not been removed and is filled in with sediment.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 073-06189 | Date: 5/17/2022

Inspection Photos



Photo 2. Facing southeast along the access road . The road has not been recontoured and culverts remain.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 073-06189 | Date: 5/17/2022

Inspection Photos



Photo 3. Facing east along the access road toward the location. The road has not been recontoured and culverts remain.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 073-06189 | Date: 5/17/2022

Inspection Photos



Photo 4. Facing east at the location. The location has not been reclaimed and soils are bare of vegetation.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 073-06189 | Date: 5/17/2022

Inspection Photos



Photo 5. There is electric utilizes and a fence in disrepair that remain at the location. All equipment should have been removed within 3 months of abandonment.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 073-06189 | Date: 5/17/2022

Inspection Photos



Photo 6. Facing northwest at the location. This area approximately 150'x100' is bare of vegetation. The location has not been reclaimed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 073-06189 | Date: 5/17/2022

Inspection Photos



Photo 7. Facing toward the surrounding reference area consisting of Blue grama, Sand dropseed, among other native species.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 073-06189 | Date: 5/17/2022