

Inspection Photos
Location Name: Cundall #6-12
Location ID: 320504



Photo 1 well head



Photo 2 Trash

Inspection Photos
Location Name: Cundall #6-12
Location ID: 320504



Photo 3 Production equipment



Photo 4 Stained soil and mechanical issue Hoz heated separator

Inspection Photos
Location Name: Cundall #6-12
Location ID: 320504



Photo 5 unsafe condition ECD cement base



Photo 6 TNK BTRY

Inspection Photos
Location Name: Cundall #6-12
Location ID: 320504



Photo 7 NFPA placards faded.