

TEP  
KP 22-22  
Location # 420972



location



location

TEP  
KP 22-22  
Location # 420972



location



Valves missing caps/plugs

TEP  
KP 22-22  
Location # 420972



**Valves missing caps/plugs**



**Valves missing caps/plugs**

TEP  
KP 22-22  
Location # 420972



**Lack of stabilization/compaction**



**Lack of stabilization/compaction**

TEP  
KP 22-22  
Location # 420972



**Lack of stabilization/compaction**



**Lack of stabilization/compaction**

TEP  
KP 22-22  
Location # 420972



**Lack of stabilization/compaction**



**Cut slope erosion**

TEP  
KP 22-22  
Location # 420972



**Cut slope erosion**



**Associated equipment with unused pumps**

TEP  
KP 22-22  
Location # 420972



May 16, 2022 at 1:00:17 PM  
39.516562,-107.544339 ±4.87m  
COGCC

**Chemical containment full of fluid and unused pumps**



May 16, 2022 at 1:00:30 PM  
39.516562,-107.544339 ±4.87m  
COGCC

**Unused pumps**

TEP  
KP 22-22  
Location # 420972



Debris



Debris

TEP  
KP 22-22  
Location # 420972



**Debris**

