

Inspection Photos
Operator: Simcoe
API: 067-08883
Date: 5/18/2022



Photo 1. View of the project area from the well pad entrance facing center.



Photo 2. View of the eastern project area from the southeastern corner facing northward. Revegetation is progressing here, largely with crested wheatgrass.



Photo 3. View of hoary cress in vegetative condition observed in the southern project area. 1000s of individuals observed.



Photo 4. View of dense hoary cress in flowering condition, observed along the access road.



Photo 5. View of the reference area comprised of pinyon and juniper woodland with prickly pear, Indian ricegrass, sagebrush, antelope bitterbrush, and yucca in the understory.