

Inspection Photos  
Operator: Simcoe  
API: 067-06780  
Date: 5/18/2022



Photo 1. View of the project area from the eastern well pad entrance facing center.



Photo 2. View of the southern project area from the southeastern corner facing westward. Revegetation is progressing here, largely with rubber rabbitbrush and western wheatgrass.




Photo 3. View of hoary cress in vegetative condition observed in the southern project area. 1000s of individuals observed.



Photo 4. View of the reference area comprised of pinyon and juniper woodland with prickly pear, Indian ricegrass, sagebrush, antelope bitterbrush, and yucca in the understory.