

Inspection Photos
Operator: Simcoe
API: 067-09662
Date: 5/18/2022



Photo 1. View of the project area from the southwestern corner facing center.



Photo 2. View of the southern project area from the southwestern corner facing eastward. Revegetation is progressing here, largely with blue grama, crested wheatgrass, and western wheatgrass.



Photo 3. View of the western project area from the southwestern corner facing northward. Unused pipes stored along the western edge of the working area.



Photo 4. View of the reference area comprised of pinyon and juniper woodland with prickly pear, Indian ricegrass, sagebrush, antelope bitterbrush, and yucca in the understory.