

Inspection Photos  
Operator: Simcoe  
API: 067-07010  
Date: 5/18/2022



Photo 1. View of the project area from the well pad entrance facing center.



Photo 2. View of hoary cress along the western edge of the working area. Approx. 100 individuals observed.



Photo 3. View of the northern project area from the northwestern corner facing eastward. Scattered wood debris and cinder blocks need to be removed and properly stored/disposed of.



Photo 4. View of the reference area comprised of irrigated grass field.