

Inspection Photos
Operator: Simcoe
API: 067-08945
Date: 5/18/2022



Photo 1. View of the project area from the well pad entrance facing center.



Photo 2. View of the eastern project area from the southeastern corner facing northward. Revegetation is progressing with western wheatgrass and crested wheatgrass.



Photo 3. View of weed and trash debris within the southern silt trap.



Photos 4-6. View of the trash and weed debris within the interim reclamation area and along the eastern fenceline.



Photo 7. View of the reference area comprised of pinyon and juniper woodland with western wheatgrass and smooth brome observed in the understory along with Indian ricegrass and prickly pear.