

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/19/2022

Submitted Date:

05/19/2022

Document Number:

702400504

**FIELD INSPECTION FORM**Loc ID 305691 Inspector Name: Revas, Robbie On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 47120

Name of Operator: KERR MCGEE OIL &amp; GAS ONSHORE LP

Address: P O BOX 173779

City: DENVER State: CO Zip: 80217-

**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

12 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone | Email                    | Comment                         |
|--------------|-------|--------------------------|---------------------------------|
| ,            |       | COGCCInspections@Oxy.com | <a href="#">All Inspections</a> |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name    | Insp Status |
|-------------|------|--------|-------------|------------|-----------|------------------|-------------|
| 431665      | WELL | PR     | 09/01/2021  | OW         | 123-36718 | CROWDER 16N-19HZ | PR          |
| 431666      | WELL | PR     | 09/01/2021  | OW         | 123-36719 | CROWDER 16C-19HZ | PR          |
| 431667      | WELL | PR     | 07/01/2019  | OW         | 123-36720 | CROWDER 38N-19HZ | PR          |
| 431668      | WELL | PR     | 07/01/2021  | OW         | 123-36721 | CROWDER 15N-18HZ | PR          |
| 431672      | WELL | PR     | 08/27/2013  | OW         | 123-36724 | CROWDER 36N-18HZ | PR          |
| 431673      | WELL | PR     | 03/01/2019  | OW         | 123-36725 | CROWDER 15C-18HZ | PR          |

**General Comment:**

**Location**Overall Good: ☒

|                      |              |       |  |
|----------------------|--------------|-------|--|
| <b>Signs/Marker:</b> |              |       |  |
| Type                 | WELLHEAD     |       |  |
| Comment:             | adequate x 6 |       |  |
| Corrective Action:   |              | Date: |  |

|                           |             |
|---------------------------|-------------|
| Emergency Contact Number: |             |
| Comment:                  |             |
| Corrective Action:        | Date: _____ |

Overall Good: ☒

|                |      |        |  |  |
|----------------|------|--------|--|--|
| <b>Spills:</b> |      |        |  |  |
| Type           | Area | Volume |  |  |

In Containment: No

Comment: \_\_\_\_\_

☐ Multiple Spills and Releases?

|                    |              |       |  |
|--------------------|--------------|-------|--|
| <b>Fencing/:</b>   |              |       |  |
| Type               | WELLHEAD     |       |  |
| Comment:           | Ag Panel x 2 |       |  |
| Corrective Action: |              | Date: |  |

|                           |                               |       |                 |
|---------------------------|-------------------------------|-------|-----------------|
| <b>Equipment:</b>         |                               |       | corrective date |
| Type: Bradenhead          | # 6                           |       |                 |
| Comment:                  | all appear plumbed to surface |       |                 |
| Corrective Action:        |                               | Date: |                 |
| Type: Plunger Lift        | # 6                           |       |                 |
| Comment:                  |                               |       |                 |
| Corrective Action:        |                               | Date: |                 |
| Type: Ancillary equipment | # 6                           |       |                 |
| Comment:                  | automation                    |       |                 |
| Corrective Action:        |                               | Date: |                 |

|                    |    |       |  |
|--------------------|----|-------|--|
| <b>Venting:</b>    |    |       |  |
| Yes/No             | NO |       |  |
| Comment:           |    |       |  |
| Corrective Action: |    | Date: |  |

|                    |  |       |  |
|--------------------|--|-------|--|
| <b>Flaring:</b>    |  |       |  |
| Type               |  |       |  |
| Comment:           |  |       |  |
| Corrective Action: |  | Date: |  |

**Inspected Facilities**

Facility ID: 431665 Type: WELL API Number: 123-36718 Status: PR Insp. Status: PR

**Producing Well**Comment: PR

Corrective Action:

Date:

**BradenHead**Date of Last Brhd Test: 12/08/2021 Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: NONEEnd Surf Csg Pressure: --

Comment:

Corrective Action:

Date:

Facility ID: 431666 Type: WELL API Number: 123-36719 Status: PR Insp. Status: PR

**Producing Well**Comment: PR

Corrective Action:

Date:

**BradenHead**Date of Last Brhd Test: 10/18/2021 Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 4 Fluid Type: WaterEnd Surf Csg Pressure: --

Comment:

Corrective Action:

Date:

Facility ID: 431667 Type: WELL API Number: 123-36720 Status: PR Insp. Status: PR

**Producing Well**Comment: PR

Corrective Action:

Date:

**BradenHead**Date of Last Brhd Test: 12/07/2021 Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 1 Fluid Type: NONEEnd Surf Csg Pressure: --

Comment:

Corrective Action:

Date:

Facility ID: 431668 Type: WELL API Number: 123-36721 Status: PR Insp. Status: PR

**Producing Well**Comment: PR

Corrective Action:

Date:

**BradenHead**

Date of Last Brhd Test: 12/28/2021 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 14 Fluid Type: NONE

End Surf Csg Pressure: 0

Comment: Corrective Action: Date: 

Facility ID: 431672 Type: WELL API Number: 123-36724 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR

Corrective Action: Date: **BradenHead**

Date of Last Brhd Test: 05/12/2021 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 1 Fluid Type: None

End Surf Csg Pressure: --

Comment: Corrective Action: Date: 

Facility ID: 431673 Type: WELL API Number: 123-36725 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR

Corrective Action: Date: **BradenHead**

Date of Last Brhd Test: 10/20/2021 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 19 Fluid Type: Water

End Surf Csg Pressure: --

Comment: Corrective Action: Date:

**Reclamation - Storm Water - Pit****Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Gravel           | Pass            |                         |                       |               |                          |         |

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

| Comment  | User   | Date       |
|--|--------|------------|
| <p>COGCC Inspection Report Summary</p> <p>On Thursday 5-19-2022 at approximately 1245 hrs. I, Inspector Robbie Revas, Conducted an on-site inspection:</p> <p>Operator: Oxy/Kerr McGee</p> <p>Location name: Crowder 38N-19HZ</p> <p>API #05-123-36720</p> <p>County: Weld</p> <p>Weather: Clear.</p> <p>Location: Dry.</p> <p>While there, I observed a Multi-well Pad, PR at the time of inspection.</p> <p>During this inspection, I observed no compliance issues:</p> <p>See attached photos.</p> <p>No follow up site inspection is needed to ensure that the addressed Compliance issues comply with COGCC rules.</p> | revasr | 05/19/2022 |

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description   | URL   |
|--------------|---------------|---|
| 702400505    | location pics | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5758629">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5758629</a> |