

FORM
INSPRev
X/20State of Colorado
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/17/2022

Submitted Date:

05/19/2022

Document Number:

700704217

FIELD INSPECTION FORM

 Loc ID 335127 Inspector Name: Ramsey, Scott On-Site Inspection 2A Doc Num: _____
Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 14 Number of Comments
 3 Number of Corrective Actions
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
 PREVIOUS INSPECTIONS THAT HAVE NOT
 BEEN ADDRESSED ARE STILL APPLICABLE**

Operator Information:
 OGCC Operator Number: 96850
 Name of Operator: TEP ROCKY MOUNTAIN LLC
 Address: 1058 COUNTY ROAD 215
 City: PARACHUTE State: CO Zip: 81635
Contact Information:

Contact Name	Phone	Email	Comment
, TEP	970-285-9377	COGCCInspectionReports@terraep.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
287515	WELL	PR	12/10/2008	GW	045-12998	PLATZER 33D-27-692	PR
287516	WELL	PR	12/10/2008	GW	045-12997	PLATZER 33B-27-692	PR
287517	WELL	PR	03/07/2007	GW	045-12996	PLATZER FEDERAL 43B-27-692	PR
287518	WELL	PR	03/16/2007	GW	045-12995	PLATZER FEDERAL 43D-27-692	PR

General Comment:**COGCC Inspection Report Summary**

On Tuesday 5/17/2022 at approximately 1200, I, Inspector Scott Ramsey, conducted a follow up inspection at TEP Platzer, at Location # 335127 in Garfield county Colorado.

Any Corrective Actions from previous Inspections that have not been addressed are still applicable.

While there, I observed normal production operations. All meters have been calibrated on location within the past year. This location is within or in close proximity to a CPW Density/High Priority Habitat, black bear, NSO habitat, Wildlife Management. Operator (TERRA) has provided there Piceance Basin Storm water Manual of BMP's (SC-4) for a tracking pad.

C/A (Location stabilization) has not been completed from previous inspection document # 700702283.

During this inspection the following possible compliance issues were observed:

1. Stored equipment (Trailer and ECD is disconnected from tanks and gas)
2. Erosion on access road.
3. Location shows signs of lack of stabilization/compaction.
4. Some cut slope erosion.
5. Random debris.

Refer to photograph of observed compliance issue.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

This is a summary of inspection report.

Location

Lease Road:			
Type	Access		
comment:	See stormwater		
Corrective Action			Date:

Overall Good:

Signs/Marker:			
Type	CONTAINERS		
Comment:			
Corrective Action:			Date:
Type	OTHER		
Comment:	Separator units include attached storage tanks. The sight glass located on the side of the unit indicates the storage tank is full of fluid. Labeling or markers are present to identify a potential hazard or the contents of the storage tank.		
Corrective Action:			Date:
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:			Date:
Type	BATTERY		
Comment:			
Corrective Action:			Date:
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:

Emergency Contact Number:			
Comment:	911		
Corrective Action:			Date: _____

Good Housekeeping:			
Type	DEBRIS		
Comment:	Random debris.		
Corrective Action:	Remove debris		Date: <u>05/31/2022</u>
Type	STORAGE OF SUPL		
Comment:	Stored equipment (Trailer and ECD is disconnected from tanks and gas)		
Corrective Action:	Remove stored equipment		Date: <u>08/18/2022</u>

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No _____

Comment: _____

Multiple Spills and Releases?

Fencing/:					
Type	WELLHEAD				
Comment:					
Corrective Action:				Date:	
Type	TANK BATTERY				
Comment:					
Corrective Action:				Date:	
Type	IGNITOR/COMBUSTOR				
Comment:					
Corrective Action:				Date:	
Type	SEPARATOR				
Comment:					
Corrective Action:				Date:	

Equipment:					corrective date
Type: Emission Control Device	# 1				
Comment:	See stored equipment				
Corrective Action:				Date:	
Type: Horizontal Heated Separator	# 4				
Comment:					
Corrective Action:				Date:	
Type: Plunger Lift	# 1				
Comment:					
Corrective Action:				Date:	
Type: Bradenhead	# 4				
Comment:					
Corrective Action:				Date:	
Type: Ancillary equipment	# 2				
Comment:	1 500 gallon methanol tank in metal containment and 1 chemical tank in plastic containment				
Corrective Action:				Date:	
Type: Bird Protectors	# 4				
Comment:					
Corrective Action:				Date:	

Tanks and Berms:						
Contents	#	Capacity	Type	Tank ID	SE GPS	
CONDENSATE	4	300 BBLs	STEEL AST		,	
Comment:	1 Tank is heated					
Corrective Action:					Date:	

Paint	
Condition	Adequate

Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth				
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities									
Facility ID:	<u>287515</u>	Type:	<u>WELL</u>	API Number:	<u>045-12998</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
<u>Producing Well</u>									
Comment:	<u>Producing</u>				Date:				
Corrective Action:					Date:				
Facility ID:	<u>287516</u>	Type:	<u>WELL</u>	API Number:	<u>045-12997</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
<u>Producing Well</u>									
Comment:	<u>Producing</u>				Date:				
Corrective Action:					Date:				
Facility ID:	<u>287517</u>	Type:	<u>WELL</u>	API Number:	<u>045-12996</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
<u>Producing Well</u>									
Comment:	<u>Producing</u>				Date:				
Corrective Action:					Date:				
Facility ID:	<u>287518</u>	Type:	<u>WELL</u>	API Number:	<u>045-12995</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
<u>Producing Well</u>									
Comment:	<u>Producing</u>				Date:				
Corrective Action:					Date:				

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:
 1. Erosion on access road.
 2. Location shows signs of lack of stabilization/compaction.
 3. Some cut slope erosion.

Corrective Action: **Install or repair required BMPs**

Date: 06/30/2022

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
700704222	Photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5758725