

FORM

6

Rev
11/20

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



DE	ET	OE	ES
----	----	----	----

Replug By Other Operator

Document Number:

402894517

Date Received:

12/13/2021

WELL ABANDONMENT REPORT

This form is to be submitted as an Intent to Abandon whenever an abandonment is planned on a borehole. After the abandonment is complete, this form shall again be submitted as a Subsequent Report of the actual work completed. The approved intent shall be valid for six months after the approval date, after that period, a new intent will be required. Attachments required with the Intent to Abandon are wellbore diagrams of the current configuration and the proposed configuration with plugs set.

A Subsequent Report of Abandonment shall indicate the actual work completed. Attachments required with a Subsequent Report are a wellbore diagram showing plugs that were set and casing remaining in the hole, the job summaries from all plugging contractors used, including wireline and cementing (third party verification) and any logs that may have been run during abandonment.

OGCC Operator Number: 10459

Contact Name: Kaleb Roush

Name of Operator: EXTRACTION OIL & GAS INC

Phone: (303) 312-8184

Address: 370 17TH STREET SUITE 5200

Fax:

City: DENVER

State: CO

Zip: 80202

Email: kroush@civiresources.com

For "Intent" 24 hour notice required,

Name: Santistevan, Brittani

Tel: (720) 471-1110

COGCC contact:

Email: brittani.santistevan@state.co.us

Type of Well Abandonment Report:



Notice of Intent to Abandon



Subsequent Report of Abandonment

API Number 05-123-05370-00

Well Name: MCMURRAY

Well Number: 1

Location: QtrQtr: SWNW

Section: 15

Township: 7N

Range: 67W

Meridian: 6

County: WELD

Federal, Indian or State Lease Number:

Field Name: WILDCAT

Field Number: 99999

Only Complete the Following Background Information for Intent to Abandon

Latitude: 40.575982

Longitude: -104.886427

GPS Data: GPS Quality Value:

Type of GPS Quality Value:

Date of Measurement:

Reason for Abandonment:


☐ Production Sub-economic

☐ Mechanical Problems

☒ Other Re-entry for Walt HZ pad development

Casing to be pulled:


☒ No

Estimated Depth:

Fish in Hole:


☒ No

If yes, explain details below

Wellbore has Uncemented Casing leaks:


☒ No

If yes, explain details below

Details:

Current and Previously Abandoned Zones

Formation	Perf. Top	Perf. Btm	Abandoned Date	Method of Isolation	Plug Depth

Total: 0 zone(s)

Casing History

Casing Type	Size of Hole	Size of Casing	Grade	Wt/Ft	Csg/Liner Top	Setting Depth	Sacks Cmt	Cmt Btm	Cmt Top	Status
SURF	12+1/4	10+3/4	NA	32	0	407	450	407	0	VISU
OPEN HOLE	8+3/4				407	9035				

Plugging Procedure for Intent and Subsequent Report

CIBP #1: Depth _____ with _____ sacks cmt on top. CIBP #2: Depth _____ with _____ sacks cmt on top.
CIBP #3: Depth _____ with _____ sacks cmt on top. CIBP #4: Depth _____ with _____ sacks cmt on top.
CIBP #5: Depth _____ with _____ sacks cmt on top.

NOTE: Two(2) sacks cement required on all CIBPs.

Set 125 sks cmt from 2600 ft. to 2400 ft. Plug Type: OPEN HOLE Plug Tagged: ☒

Set 125 sks cmt from 850 ft. to 650 ft. Plug Type: OPEN HOLE Plug Tagged: ☒

Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged: ☐

Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged: ☐

Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged: ☐

Perforate and squeeze at _____ ft. with _____ sacks. Leave at least 100 ft. in casing _____ CICR Depth

Perforate and squeeze at _____ ft. with _____ sacks. Leave at least 100 ft. in casing _____ CICR Depth

Perforate and squeeze at _____ ft. with _____ sacks. Leave at least 100 ft. in casing _____ CICR Depth

(Cast Iron Cement Retainer Depth)

Set 105 sacks half in. half out surface casing from 460 ft. to 300 ft. Plug Tagged: ☒

Set 15 sacks at surface

Cut four feet below ground level, weld on plate Above Ground Dry-Hole Marker: ☐ Yes ☐ No

Set _____ sacks in rat hole Set _____ sacks in mouse hole

Additional Plugging Information for Subsequent Report Only

Casing Recovered: _____ ft. of _____ inch casing

Surface Plug Setting Date: _____ Cut and Cap Date: _____ Number of Days from Setting Surface Plug to Capping or Sealing the Well: _____

*Wireline Contractor: _____

*Cementing Contractor: _____

Type of Cement and Additives Used: _____

Flowline/Pipeline has been abandoned per Rule 1105 ☐ Yes ☐ No

Technical Detail/Comments:

WBD shows 32.75# casing, the actual casing is 32# per this form's entry (unable to manually change on backend)

Hole sizes are assumed.

Need to re-enter and adequately re-plug prior to hydraulic stimulation of Extraction's Walt pad.

I hereby certify all statements made in this form are, to the best of my knowledge, true, correct, and complete.

Signed: _____ Print Name: Kaleb Roush

Title: Production Engineer Date: 12/13/2021 Email: kroush@civiresources.com

Based on the information provided herein, this Well Abandonment Report (Form 6) complies with COGCC Rules and applicable orders and is hereby approved.

COGCC Approved: JENKINS, STEVE Date: 1/11/2022

CONDITIONS OF APPROVAL, IF ANY:

Expiration Date: 7/10/2022

COA Type	Description
	Submit "as drilled" GPS data on Subsequent Report of Abandonment. GPS data must meet the requirements of Rule 216.
	1) Provide 48 hours notice of plugging MIRU via electronic Form 42. 2) After placing the shallowest hydrocarbon isolating plug (2600'), operator must wait a sufficient time to confirm static conditions. If at any time after placing this plug there is evidence of pressure or of fluid migration, contact COGCC engineering before continuing operations. 3) Prior to placing the 460' plug: verify that all fluid migration (liquid and gas) has been eliminated. If evidence of fluid migration or pressure remains, contact COGCC Engineer for an update to plugging orders. 4) After isolation has been verified, pump plug and displace. If cement is not circulated to surface, shut-in, WOC 4 hours then tag plug – must be at 357' or shallower and provide 10 sx plug at the surface. 5) Leave at least 100' of cement in the wellbore for each plug. 6) With the Form 6 SRA operator must provide written documentation which positively affirms each COA has been addressed.
	Operator will ensure adequate stormwater controls to prevent impacted stormwater and sediment from entering surface waters.
	Operator will implement measures to control emissions to protect health and safety, and to ensure that vapors and odors from well plugging operations do not constitute a nuisance or hazard to public health, welfare, and the environment.

Attachment List

Att Doc Num	Name
402894517	WELL ABANDONMENT REPORT (INTENT)
402894545	SURFACE OWNER CONSENT
402894579	WELLBORE DIAGRAM
402897297	LOCATION PHOTO
402922772	FORM 6 INTENT SUBMITTED

Total Attach: 5 Files

General Comments

User Group	Comment	Comment Date
Permit	-Missing as-drilled well location. -No other forms in process. -Reviewed attachments. -Pass.	01/11/2022
Engineer	1) Deepest Water Well within 1 mile = 300'. 2) Fox Hills Bottom- N/A, per SB5.	01/04/2022
Engineer	This is a re-entry of a PA well, there is no Bradenhead valve, for testing, and there are no flowlines to be abandoned or removed.	01/04/2022
Engineer	Emailed Operator with a question on an elevation on an open hole plug. Revised 8550, to 850 per Operator, 1/04/22.	01/03/2022
OGLA	OGLA review complete.	01/03/2022

Total: 5 comment(s)