

TEP
RWF 331-27
Location # 335380



location



location

TEP
RWF 331-27
Location # 335380



location



Well heads gate and fence falling down

TEP
RWF 331-27
Location # 335380



Missing cap/plug



Lack of stabilization/compaction

TEP
RWF 331-27
Location # 335380



Lack of stabilization/compaction



Well head entrance gate

TEP
RWF 331-27
Location # 335380



Debris

