

Location

Overall Good:

Signs/Marker:			
Type	WELLHEAD		
Comment:	adequate		
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:	<input type="text"/>		
Corrective Action:	<input type="text"/>		Date: _____

Good Housekeeping:			
Type	OTHER		
Comment:	Stained concrete due to leaking seal		
Corrective Action:	Comply with Rule 1002..(2).D: Self-inspection, maintenance, and good housekeeping procedures and schedules.		Date: <u>05/30/2022</u>
Type	OTHER		
Comment:	Mechanical Conditions seal on PJ gear box is leaking		
Corrective Action:	Securely fasten all valves, pipes, fittings, and Production Facilities to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 608.e.		Date: <u>06/23/2022</u>

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:			
Type	OTHER		
Comment:	ancillary equipment has fabricated steel pipe		
Corrective Action:		Date:	
Type	PUMP JACK		
Comment:	Fabricated angle iron		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Ancillary equipment	# 1		
Comment:	electric panel meter box and transformers		
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Prime Mover	# 1		

Comment:	electric motor		
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	appears plumbed to surface		
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 241021 Type: WELL API Number: 123-08809 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 10/11/2021 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: -- Fluid Type: _____

End Surf Csg Pressure: --

Comment:

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary On Monday 5-23-2022 at approximately 1240 hrs. I, Inspector Robbie Revas, Conducted an on-site inspection: Routine Operator: KP Kauffman Location name: Christiansen 2 API #05-123-08809 County: Weld Weather: Clear. Location: Dry. While there, I observed a wellsite, PR at the time of inspection. During this inspection, I observed the following possible compliance issues: 1002..(2).D Housekeeping: stained concrete at base of the PJ due to leakng seal, CA date 5-30-2022 608.e Housekeeping: Mechanical Condition, Seal on PJ gear box is leaking, CA date 6-23-2022. See attached photos. A follow up site inspection is needed to ensure that the addressed Compliance issues comply with COGCC rules.</p>	revasr	05/23/2022

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
702400525	location pics	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5761235