



Location					
Overall Good: <input checked="" type="checkbox"/>					
<b>Signs/Marker:</b>					
Type	WELLHEAD				
Comment:	adequate, fading and beginning to peel will need to be replaced in the near future				
Corrective Action:					Date:
Emergency Contact Number:					
Comment:					Date:
Corrective Action:					Date: _____
<b>Good Housekeeping:</b>					
Type	UNUSED EQUIPMENT				
Comment:	Pump jack sitting disassembled in the weeds.				
Corrective Action:	Comply with Rule 606				Date: <u>05/15/2022</u>
Overall Good: <input type="checkbox"/>					
<b>Spills:</b>					
Type	Area	Volume			
In Containment: No					
Comment:					
<input type="checkbox"/> Multiple Spills and Releases?					
<b>Fencing/:</b>					
Type					
Comment:					
Corrective Action:					Date:
<b>Equipment:</b>					
Type: Bradenhead	# 1				corrective date
Comment:	appears plumbed to surface				
Corrective Action:					Date:
Type: Pump Jack	# 1				
Comment:	unused disassembled in the weeds				
Corrective Action:					Date:
Type: Plunger Lift	# 1				
Comment:					
Corrective Action:					Date:
<b>Tanks and Berms:</b>					
Contents	#	Capacity	Type	Tank ID	SE GPS
Comment:	See related inspection Doc #693503336 for information concerning shared facilities and equipment.				
Corrective Action:					Date:

<b>Paint</b>				
Condition				
Other (Content)				
Other (Capacity)				
Other (Type)				
<b>Berms</b>				
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:
<b>Venting:</b>				
Yes/No	NO			
Comment:				
Corrective Action:				Date:
<b>Flaring:</b>				
Type				
Comment:				
Corrective Action:				Date:

**Inspected Facilities**

Facility ID: 241522 Type: WELL API Number: 123-09311 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR

Corrective Action:

Date:

**BradenHead**

Date of Last Brhd Test: 10/21/2021 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: \_\_\_\_\_

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary                      On Tuesday 5/25/2022 at approximately 1030 hrs. I, Inspector Robbie Revas, Conducted an on-site inspection: Follow up to inspection Doc # 699305057.                      Operator: KP Kauffman                      Location: Pace-Connelly 1                      API # 05-123-09311                      County: Weld                      While there, I observed a wellsite, PR at the time of inspection.                      During this inspection the following possible compliance issue was observed and is now delinquent:                      606 Housekeeping: Unused Pump Jack equipment on location, CA date 5-15-2022.                      See attached photos.                      Location: Dry, Weather: Clear.                      A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with COGCC rules.                      This is a summary of inspection report.</p>	revasr	05/25/2022

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
702400535	location pics	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5763416">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5763416</a>