

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/25/2022

Submitted Date:

05/25/2022

Document Number:

702400536**FIELD INSPECTION FORM**Loc ID 318533 Inspector Name: Revas, Robbie On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 46290

Name of Operator: KP KAUFFMAN COMPANY INC

Address: 1700 LINCOLN ST STE 4550

City: DENVER State: CO Zip: 80203

**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

9 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		cogcc@kpk.com	<a href="#">All Inspections</a>
,		rwatzman@kpk.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
241522	WELL	PR	08/01/2018	OW	123-09311	PACE-CONNELLY 1	PR

**General Comment:**

**Location**Overall Good: ☒

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	adequate, fading and beginning to peel will need to be replaced in the near future		
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:			
Corrective Action:			Date: _____

<b>Good Housekeeping:</b>			
Type	OTHER		
Comment:	Mechanical issue, Leak around the tubing coming out of the bradenhead just below the master valve		
Corrective Action:	Comply with Rule 608.e: Securely fasten all valves, pipes, fittings, and Production Facilities to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition.		Date: 06/25/2022

Overall Good: ☐

<b>Spills:</b>				
Type	Area	Volume		

In Containment: No

Comment: \_\_\_\_\_

☐ Multiple Spills and Releases?

<b>Fencing/:</b>			
Type			
Comment:			
Corrective Action:			Date:

<b>Equipment:</b>				corrective date
Type: Plunger Lift	# 1			
Comment:				
Corrective Action:			Date:	
Type: Bradenhead	# 1			
Comment:	appears plumbed to surface			
Corrective Action:			Date:	
Type: Pump Jack	# 1			
Comment:	Pump jack sitting disassembled in the weeds.			
Corrective Action:			Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS

Comment:	See related inspection Doc #693503336 for information concerning shared facilities and equipment.				
Corrective Action:					Date:
<b>Paint</b>					
Condition					
Other (Content)					
Other (Capacity)					
Other (Type)					
<b>Berms</b>					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:					
Corrective Action:					Date:
<b>Venting:</b>					
Yes/No	NO				
Comment:					
Corrective Action:					Date:
<b>Flaring:</b>					
Type					
Comment:					
Corrective Action:					Date:

**Inspected Facilities**Facility ID: 241522 Type: WELL API Number: 123-09311 Status: PR Insp. Status: PR**Producing Well**Comment: PR

Corrective Action:

Date:

**BradenHead**Date of Last Brhd Test: 10/21/2021 Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: \_\_\_\_\_End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On Tuesday 5/25/2022 at approximately 1130 hrs. I, Inspector Robbie Revas, Conducted an on-site inspection:</p> <p>Operator: KP Kauffman</p> <p>Location: Pace-Connelly 1</p> <p>API # 05-123-09311</p> <p>County: Weld</p> <p>While there, I observed a wellsite, PR at the time of inspection.</p> <p>During this inspection the following possible compliance issues were observed:</p> <p>608.e Mechanical Issue: Leak around the tubing coming out of the bradenhead just below the master valve, CA date 6-25-2022.</p> <p>See attached photos.</p> <p>Location: muddy, Weather: clear/partly cloudy.</p> <p>I spoke with Mani Silva with KP Kauffman at 1130 hrs. about the Mech. issue and he said he'd get someone out to look at it.</p> <p>A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of inspection report.</p>	revasr	05/25/2022

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
702400537	location pics	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5763417">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5763417</a>
702400538	leak vid	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5763418">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5763418</a>