

Inspection Photos
Operator: Hilcorp Energy
API: 067-05008
Date: 5/24/2022



Photo 1. View of the project area from the well pad entrance facing center.



Photo 2. View of the northern project area from the northeastern corner facing westward. Revegetation is progressing within crested wheatgrass, smooth brome, western wheatgrass, and rubber rabbitbrush.



Photo 3. View of the western project area from the northwestern corner facing southward.



Photo 4. View of area within the western interim reclamation area where tire tracks observed and are resulting in site degradation.



Photo 5. Another view of tracking within the western project area, facing center.



Photo 6. View of reference area comprised of pinyon and juniper woodland with gambel oak, Indian ricegrass, antelope bitterbrush, mountain mahogany, and sulfur flower.