

Inspection Photos

Operator: Hilcorp Energy
API: 067-09345
Date: 5/24/2022



Photo 1. View of the project area from the southern entrance facing center. .



Photo 2. View of the eastern project area from the southeastern corner facing northward. Revegetation is progressing within crested wheatgrass, western wheatgrass, and sand dropseed.



Photo 3. View of unused equipment stored in the eastern project area, needs to be removed.



Photo 4. View of vehicle tracking observed within the interim reclamation area, resulting in damage to vegetation and site degradation.



Photo 5. View of more vehicle tracking observed within the interim reclamation area, resulting in damaged vegetation.



Photo 6. View of reference area comprised of pinyon and juniper woodland with gambel oak, Indian ricegrass, antelope bitterbrush, mountain mahogany, and sulfur flower.