

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/25/2022

Submitted Date:

05/26/2022

Document Number:

690103038

FIELD INSPECTION FORMLoc ID 319154 Inspector Name: Maclaren, Joe On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 100322

Name of Operator: NOBLE ENERGY INC

Address: 2001 16TH STREET SUITE 900

City: DENVER State: CO Zip: 80202

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

2 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
		rbucogccinspectionreports@c hevron.onmicrosoft.com	
Schlagenhauf, Mark		mark.schlagenhauf@state.co. us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
243000	WELL	SI	10/01/2021	GW	123-10791	HANSCOME 2	SI
247016	WELL	TA		GW	123-14813	HANSCOME 11-7	TA

General Comment:COGCC Engineering Integrity Inspection; Flowline Inspection
Photos Uploaded

Inspected FacilitiesFacility ID: 243000 Type: WELL API Number: 123-10791 Status: SI Insp. Status: SI**Flowline**

#1	Type:Non-Well Site	of Lines	
----	--------------------	----------	--

Flowline Description

Flowline Type: Non-Well Site Size: 2" Material: Carbon Steel
 Variance: Age: Contents:

Integrity Summary

Failures: Spills: Repairs Made:
 Coatings: H2S: Cathodic Protection:

Pressure Testing

Witnessed: Test Result: Charted:

COGCC Rules(check all that apply)

☐ 1101. Installation and Reclamation ☒ 1102. Operations, Maintenance, and Repair ☐ 1103. Abandonment

Comment: Wells (Hanscome 2, 11-7) are SI/ TA. Battery services (2) wells as listed above; Signage at battery indicates long term shut in of location. OOSLAT (locks and tags) observed on off location flowline endpoints on valves at wellheads and inlet to production equipment (heated horizontal separator/ flowline manifold). The GMR is shut in/ OOSLAT. No Noble Energy personnel were on location at the time of this field inspection.

Corrective Action:

Date:

Facility ID: 247016 Type: WELL API Number: 123-14813 Status: TA Insp. Status: TA**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
690103045	Signage at tank battery	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5764601
690103046	Flowline manifold at inlet to HHS; OOSLAT	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5764602
690103047	Wellhead SI; OOSLAT	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5764603