

TEP
Brynildson 13C
Location # 335379



location



location

TEP
Brynildson 13C
Location # 335379



location



location

TEP
Brynildson 13C
Location # 335379



Previous inspection of tank label



Recent inspection of tank label

TEP
Brynildson 13C
Location # 335379



location



BMP's Failing and debris

TEP
Brynildson 13C
Location # 335379



BMP's Failing and debris



BMP's Failing and debris

TEP
Brynildson 13C
Location # 335379



Previous photo of stored equipment



Recent photo of stored equipment

TEP
Brynildson 13C
Location # 335379



**Previous inspection of Lack of stabilization/
compaction/ degradation**



**Recent photo of Lack of stabilization/ compaction/
degradation**

TEP
Brynildson 13C
Location # 335379



**Previous inspection of Lack of stabilization/
compaction/ degradation**



**Recent photo of Lack of stabilization/ compaction/
degradation**

TEP
Brynildson 13C
Location # 335379



Lack of stabilization/ compaction/ degradation



Lack of stabilization/ compaction/ degradation

TEP
Brynildson 13C
Location # 335379



Lack of stabilization/ compaction/ degradation



Tracking

TEP
Brynildson 13C
Location # 335379



Tracking



Tracking