

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/25/2022

Submitted Date:

05/27/2022

Document Number:

700704258

**FIELD INSPECTION FORM**

Loc ID 335379 Inspector Name: Ramsey, Scott On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_

**Operator Information:**

OGCC Operator Number: 96850

Name of Operator: TEP ROCKY MOUNTAIN LLC

Address: 1058 COUNTY ROAD 215

City: PARACHUTE State: CO Zip: 81635

**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION  
☒ FOLLOW UP INSPECTION REQUIRED  
☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

22 Number of Comments

2 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
, COGCC		shaun.kellerby@state.co.us	
, TEP	970-285-9377	COGCCInspectionReports@terraep.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
263512	WELL	PR	04/05/2005	GW	045-08133	BRYNILDSON 13C-20-692	PR
276580	WELL	PR	03/13/2009	GW	045-10488	BRYNILDSON 13B-20-692	PR
276581	WELL	PR	05/31/2005	GW	045-10487	BRYNILDSON 12A-20-692	PR
276741	WELL	PR	03/01/2009	GW	045-10513	BRYNILDSON 13D-20-692	PR
297757	WELL	PR	03/16/2009	GW	045-16952	BRYNILDSON 12C-20-692	PR
297758	WELL	PR	03/06/2009	GW	045-16953	BRYNILDSON 22A-20-692	PR
297759	WELL	PR	03/01/2009	GW	045-16954	BRYNILDSON 22B-20-692	PR
297760	WELL	PR	03/01/2009	GW	045-16955	BRYNILDSON 22C-20-692	PR
297761	WELL	PR	03/11/2009	GW	045-16956	BRYNILDSON 23B-20-692	PR
297762	WELL	PR	03/05/2009	GW	045-16957	BRYNILDSON 23C-20-692	PR
297763	WELL	PR	02/25/2009	GW	045-16958	BRYNILDSON 23D-20-692	PR
297764	WELL	PR	03/10/2009	GW	045-16959	BRYNILDSON 12B-20-692	PR

**General Comment:**

COGCC Inspection Report Summary

On Wednesday 5/25/2022 at approximately 1200, I, Inspector Scott Ramsey, conducted a follow up inspection at TEP Brynildson 13C, at Location # 335379 in Garfield county Colorado.

Any Corrective Actions from previous Inspections that have not been addressed are still applicable.

While there, I observed normal production operations. All meters have been calibrated on location within the past year. This location is within or in close proximity to a CPW Density/High Priority Habitat, black bear, NSO habitat, Wildlife Management. Operator (TERRA) has provided there Piceance Basin Storm water Manual of BMP's (SC-4) for a tracking pad.

Operator submitted FIRR stating C/A's have been completed document # 402951764.

C/A's (stored equipment and lack of stabilization) from previous inspection document # 700703713 have NOT been completed. C/A (missing plugs/caps on tank valves) has been completed.

During this inspection the following possible compliance issues were observed:

1. Location still shows signs of lack of stabilization/ compaction/ degradation. C/A date 4/15/2022 from previous inspection remains the same.
2. Waddles are failing.
3. Stored equipment (ECD is disconnected from everything) C/A date 3/18/2022 remains the same from previous inspection.

Refer to photograph of observed compliance issue.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

This is a summary of inspection report.

**Location****Lease Road:**

Type	Access		
comment:			
Corrective Action	L	Date:	

Overall Good: ☐**Signs/Marker:**

Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Tank labeling is still falling off from previous inspection.		
Corrective Action:		Date:	
Type	OTHER		
Comment:	Separator units include attached storage tanks. The sight glass located on the side of the unit indicates the storage tank is full of an unknown fluid. No form of labeling or markers are present to identify a potential hazard or the contents of the storage tank.		
Corrective Action:		Date:	

**Emergency Contact Number:**

Comment:	911		
Corrective Action:		Date:	

**Good Housekeeping:**

Type	STORAGE OF SUPL		
Comment:	Stored equipment (ECD is disconnected from everything) C/A date 3/18/2022 remains the same from previous inspection.		
Corrective Action:	Remove stored equipment or put into service	Date:	03/18/2022

Overall Good: ☐**Spills:**

Type	Area	Volume		
In Containment:	No			
Comment:				
<input type="checkbox"/> Multiple Spills and Releases?				

**Fencing/:**

Type	SEPARATOR		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			

Corrective Action:		Date:	
Type	IGNITOR/COMBUSTOR		
Comment:			
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Ancillary equipment	# 2		
Comment:	chemical tanks in plastic containments		
Corrective Action:		Date:	
Type: Bird Protectors	# 10		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 12		
Comment:			
Corrective Action:		Date:	
Type: Emission Control Device	# 1		
Comment:	See storage of equipment		
Corrective Action:		Date:	
Type: Bradenhead	# 12		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 12		
Comment:			
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	3	500 BBLS	HEATED STEEL AST		,
Comment:	2 tanks are NOT heated				
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	3	500 BBLS	HEATED STEEL AST		,

Comment:	1 tank is NOT heated		
Corrective Action:		Date:	

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	263512	Type:	WELL	API Number:	045-08133	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing								
Corrective Action:					Date:				
Facility ID:	276580	Type:	WELL	API Number:	045-10488	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing								
Corrective Action:					Date:				
Facility ID:	276581	Type:	WELL	API Number:	045-10487	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing								
Corrective Action:					Date:				
Facility ID:	276741	Type:	WELL	API Number:	045-10513	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing								
Corrective Action:					Date:				
Facility ID:	297757	Type:	WELL	API Number:	045-16952	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing								
Corrective Action:					Date:				
Facility ID:	297758	Type:	WELL	API Number:	045-16953	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing								
Corrective Action:					Date:				
Facility ID:	297759	Type:	WELL	API Number:	045-16954	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing								
Corrective Action:					Date:				
Facility ID:	297760	Type:	WELL	API Number:	045-16955	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing								
Corrective Action:					Date:				

Facility ID:	297761	Type:	WELL	API Number:	045-16956	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

**Producing Well**

Comment: Producing

Corrective Action:

Date:

Facility ID:	297762	Type:	WELL	API Number:	045-16957	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

**Producing Well**

Comment: Producing

Corrective Action:

Date:

Facility ID:	297763	Type:	WELL	API Number:	045-16958	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

**Producing Well**

Comment: Producing

Corrective Action:

Date:

Facility ID:	297764	Type:	WELL	API Number:	045-16959	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

**Producing Well**

Comment: Producing

Corrective Action:

Date:

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Check Dams				
Compaction	Fail					
		Culverts				
		Ditches				
Sediment Traps						
Waddles	Fail					
Rip Rap						
Ditches						

Comment: 1. Location still shows signs of lack of stabilization/ compaction/ degradation. C/A date 4/15/2022 from previous inspection remains the same.  
 2. Waddles are failing.  
 3 Some evidence of tracking from location.

Corrective Action: **Install or repair required BMPs**

Date: 04/15/2022

**Pits:** ☒ NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
700704262	Photo log	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5765536">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5765536</a>