

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/23/2022

Submitted Date:

05/23/2022

Document Number:

700704234**FIELD INSPECTION FORM**

Loc ID 335332	Inspector Name: Ramsey, Scott	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	Status Summary: <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input checked="" type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED
Operator Information: OGCC Operator Number: <u>96850</u> Name of Operator: <u>TEP ROCKY MOUNTAIN LLC</u> Address: <u>1058 COUNTY ROAD 215</u> City: <u>PARACHUTE</u> State: <u>CO</u> Zip: <u>81635</u>				Findings: 12 Number of Comments 2 Number of Corrective Actions <input checked="" type="checkbox"/> Corrective Action Response Requested ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:			
Contact Name	Phone	Email	Comment
, TEP	970-285-9377	COGCCInspectionReports@terraep.com	

Inspected Facilities:							
Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
263835	WELL	PR	08/27/2002	GW	045-08143	CLOUGH RMV 150-22	PR
293566	WELL	PR	07/20/2008	GW	045-15045	CLOUGH RWF 543-22	PR
294208	WELL	PR	07/31/2008	GW	045-15316	CLOUGH RWF 343-22	PR
294209	WELL	PR	01/07/2008	GW	045-15317	CLOUGH RWF 43-22	PR
294210	WELL	PR	01/07/2008	GW	045-15318	CLOUGH RWF 443-22	PR
294211	WELL	PR	07/27/2008	GW	045-15319	CLOUGH RWF 344-22	PR

General Comment:

COGCC Inspection Report Summary
 On Monday 5/23/2022 at approximately 1000, I, Inspector Scott Ramsey, conducted a routine inspection at TEP RMV 150-22, at Location # 335332 in Garfield county Colorado.
 Any Corrective Actions from previous Inspections that have not been addressed are still applicable.
 While there, I observed normal production operations. All meters have been calibrated on location within the past year. This location is within or in close proximity to a CPW Density/High Priority Habitat, black bear, NSO habitat, Wildlife Management, Geologic Hazard area. Operator (TERRA) has provided there Piceance Basin Storm water Manual of BMP's (SC-4) for a tracking pad.
 During this inspection the following possible compliance issues were observed:
 1. Some areas of location show signs of lack of stabilization/ compaction/ degradation
 2. Well head fence panel is on ground.

Refer to photograph of observed compliance issue.
 A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.
 This is a summary of inspection report.

Location				
Lease Road:				
Type	Access			
comment:				
Corrective Action	L			Date:
Overall Good: <input type="checkbox"/>				
Signs/Marker:				
Type	CONTAINERS			
Comment:				
Corrective Action:				Date:
Type	WELLHEAD			
Comment:				
Corrective Action:				Date:
Emergency Contact Number:				
Comment:	911			
Corrective Action:				Date: _____
Good Housekeeping:				
Type	OTHER			
Comment:	Well head fence is on the ground containing well head signage			
Corrective Action:	Repair or remove fencing and provide proper signage			Date: 06/01/2022
Overall Good: <input type="checkbox"/>				
Spills:				
Type	Area	Volume		
In Containment: No				
Comment:				
<input type="checkbox"/> Multiple Spills and Releases?				
Fencing/:				
Type	WELLHEAD			
Comment:	See housekeeping			
Corrective Action:				Date:
Equipment:				
Type: Ancillary equipment	# 1			corrective date
Comment:	1 chemical tank in plastic containment			
Corrective Action:				Date:
Type: Bradenhead	# 6			
Comment:				
Corrective Action:				Date:
Type: Plunger Lift	# 6			
Comment:				

Corrective Action:		Date:	
<u>Venting:</u>			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	
<u>Flaring:</u>			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities									
Facility ID:	263835	Type:	WELL	API Number:	045-08143	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:						Date:			
Facility ID:	293566	Type:	WELL	API Number:	045-15045	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:						Date:			
Facility ID:	294208	Type:	WELL	API Number:	045-15316	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:						Date:			
Facility ID:	294209	Type:	WELL	API Number:	045-15317	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:						Date:			
Facility ID:	294210	Type:	WELL	API Number:	045-15318	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:						Date:			
Facility ID:	294211	Type:	WELL	API Number:	045-15319	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:						Date:			

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Fail					

Comment: [1. Some areas of location show signs of lack of stabilization/ compaction/ degradation](#)

Corrective Action: [Install or repair required BMPs](#)

Date: 07/01/2022

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403057236	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5761239
700704240	Photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5761224