

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/17/2022

Submitted Date:

05/23/2022

Document Number:

702800242**FIELD INSPECTION FORM**Loc ID 428571 Inspector Name: O'Malley, Anna On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10396Name of Operator: SWN PRODUCTION COMPANY LLCAddress: P.O. BOX 12359City: SPRING State: TX Zip: 77391-**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**8 Number of Comments3 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone | Email | Comment |
|--------------|-------|------------------------|---------------------------------|
| , SWN | | swnsandwash@swn.com | All Inspections |
| Pate, James | | jspconcrete@yahoo.com | Principle Agent |
| Stepp, Sarah | | wccassistant@gmail.com | All Inspections |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|----------|--------|-------------|------------|---------|---------------|-------------|
| 428571 | LOCATION | AC | | | - | SIMOES 12-30 | RI |

General Comment:

On 05/17/2022, Reclamation Specialist O'Malley conducted a reclamation and stormwater inspection at Beeman Oil & Gas LLC's Simoes /12-30 Location #428571 in Moffat County, Colorado.

The following compliance issues were observed during this inspection:

- Location signage with incorrect Operator information
- Unused pipe equipment
- Noxious weeds: hoary cress/whitetop, perennial pepperweed, houndstongue

Refer to the "Location," "Reclamation," "Stormwater" and "COGCC Comments" sections of this inspection report for additional details.

Refer to the photo-documentation of the observed compliance issues attached to this report.

Any corrective action(s) from previous inspections that have not been addressed are still applicable.

A follow up inspection on this site will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

COGCC records show the Operator for this Location as SWN Production Company LLC #10396. Form 09 (S) #403026381 to transfer Operatorship from SWN Production Company LLC to Beeman Oil & Gas LLC #7125 is in process. Until COGCC records show Beeman Oil & Gas LLC as the Operator, both Operators are included in inspection reports.

LocationOverall Good: ☐

| | | | |
|----------------------|---|-------|------------|
| Signs/Marker: | | | |
| Type | WELLHEAD | | |
| Comment: | Signage at the wellhead reads with incorrect Operator information. | | |
| Corrective Action: | Comply with 605 Rules- implement signage with correct Operator throughout Location. | Date: | 06/22/2022 |

| | | | |
|---------------------------|----------------------|--|----------------------------|
| Emergency Contact Number: | | | |
| Comment: | <input type="text"/> | | |
| Corrective Action: | <input type="text"/> | | Date: <input type="text"/> |

| | | |
|---------------------------|---|------------------|
| Good Housekeeping: | | |
| Type | STORAGE OF SUPL | |
| Comment: | It was observed in this inspection that unused piping was stored on Location. | |
| Corrective Action: | Comply with Rule 606. | Date: 06/07/2022 |

Overall Good: ☐

| | | | | |
|----------------|------|--------|--|--|
| Spills: | | | | |
| Type | Area | Volume | | |

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Venting:**

| | | |
|--------------------|--|-------|
| Yes/No | | |
| Comment: | | |
| Corrective Action: | | Date: |

Flaring:

| | | |
|--------------------|--|-------|
| Type | | |
| Comment: | | |
| Corrective Action: | | Date: |

Reclamation - Storm Water - Pit**Interim Reclamation:**

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: DRY LAND

Comment: _____

1002 SITE PREPARATION AND STABILIZATION

1002a. FENCING _____

Comment _____

Corrective Action _____

Date _____

1002b. SOIL REMOVAL AND _____

Comment _____

Corrective Action _____

Date _____

1002c. PROTECTION OF SOILS _____

Comment _____

Corrective Action _____

Date _____

1002E. SURFACE DISTURBANCE MINIMIZATION _____

Comment _____

Corrective Action _____

Date _____

1003a. Waste and Debris removed? Pass

Comment _____

Corrective Action _____

Date _____

Unused or unneeded equipment onsite? _____

Comment _____

Corrective Action _____

Date _____

Pit, cellars, rat holes and other bores closed? Pass

Comment _____

Corrective Action _____

Date _____

Guy line anchors marked? Pass

Comment _____

Corrective Action _____

Date _____

1003b. Area no longer in use? PassProduction areas stabilized ? Pass

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? In

Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATIONCropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-CroplandTop soil replaced _____ Recontoured _____ 80% Revegetation In

1003e. INTERIM VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

1003 f. Weeds Noxious weeds? F

Comment **Hoary cress/whiteweed was observed in patches in the western and southern interim areas. At the time of this inspection this species was flowering. Perennial pepperweed, ("extremely invasive" according to CO department of agriculture) was observed on the working pad area. At the time of this inspection this species was in the early stages of sending up the flowering stalk. Houndstongue was also present. All three species are CO List B Noxious Weeds.**

Interim areas to the north, west and east of the Location are very well colonized by a diversity of desirable perennial plant species. The interim area to the south has good perennial grass establishment, however some patches are dominated exclusively by purple mustard, an annual weed.

Corrective Action **Comply with Rule 1003.f and conduct weed management on the Location to prevent further establishment and spread of CO State List B Noxious Weeds; ongoing weed management required until site passes final reclamation.**

Date 05/30/2022Overall Interim Reclamation In Process**Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: DRY LAND

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

1004.d. FINAL VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

Comment: _____

Corrective Action: _____

Date _____

Overall Final Reclamation _____

Well Release on Active Location ☐Multi-Well Location ☐**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| | | | | | | |

Comment: At the time of this inspection, no stormwater issues were observed. The slopes of the Location are well vegetated with perennial plants which are sufficient to stabilize the slopes at this time. A stormwater swale is present at the west of the Location which has been installed with straw wattles for velocity check dams. The swale leads into a sediment trap and then to a rip-rap lined outlet which leads offsite. All BMPs are colonized by perennial grasses and appear to be sufficient to manage stormwater at this time.

Corrective Action: _____

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|----------------------|---|
| 403057052 | INSPECTION SUBMITTED | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5761074 |
| 702800243 | Inspection Photos | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5761073 |