

State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



OGCC RECEPTION Receive Date: 11/03/2021 Document Number: 402860957

Off-Location Flowline

The Flowline Report, Form 44, shall be submitted to register, report realignment, report removal from service, provide pre-abandonment notices, or report abandonment of Off-Location Flowlines, Flowline Systems, Produced Water Transfer Systems, or Crude Oil Transfer Lines or Systems as required by the 1100 Series Rules. The Form 44 shall also be submitted to register, report realignment, or report abandonment of Domestic Taps, and to report Grade 1 Gas Leaks from Flowlines per Rules 610 and 906.

Operator Information

OGCC Operator Number: 10459 Contact Person: Nathan Bennett Company Name: EXTRACTION OIL & GAS INC Phone: (720) 354-4616 Address: 370 17TH STREET SUITE 5200 Email: nbennett@civiresources.com City: DENVER State: CO Zip: 80202 Is the Operator a Tier One member of the Utility Notification Center of Colorado (CO811) that participates in Colorado's One Call notification system? Yes [X] No []

OFF LOCATION FLOWLINE

FLOWLINE ENDPOINT LOCATION IDENTIFICATION

Location ID: 321309 Location Type: Production Facilities Name: ROCKWELL-61S69W Number: 1SENE County: BOULDER Qtr Qtr: SENE Section: 1 Township: 1S Range: 69W Meridian: 6 Latitude: 39.994840 Longitude: -105.055840

Description of Corrosion Protection

Extraction's corrosion procedures are detailed in its Flowline Management SOP. Coating materials will be used that minimize internal and external corrosion, such as internally coated pipe or stainless steel for water service, and externally coated FBE on all buried steel pipe. If flowlines are repaired due to corrosion, Extraction will investigate the failure, promptly respond with the appropriate remedial actions and determine the root cause and apply corrective actions as necessary. Extraction retains records of its chemical program in the form of Failure Analysis Reports, records of chemical invoices and chemical delivery.

Description of Integrity Management Program

Extraction's integrity management program is detailed in its Flowline Management SOP, which covers flowline installation, operation, maintenance, inspection, testing, and repairs. Prior to beginning any project involving flowlines, Extraction ensures the project plans, flowline installation, flowline maintenance (including repairs) and all flowline inspection and testing projects meet the requirements of the Flowline Management SOP. All pressure tests on flowlines will be conducted by an independent, third party qualified to do such testing. Precautions shall be taken to protect employees and the general public.

Description of the construction method used for public by-ways, road crossings, sensitive wildlife habitats, sensitive areas, and natural and manmade watercourses (i.e., open trench, bored and cased, or bored only), if applicable.

N/A

FLOWLINE FACILITY INFORMATION

Flowline Facility ID: 460528 Flowline Type: Wellhead Line Action Type: Abandonment Verification

OFF LOCATION FLOWLINE REGISTRATION

Equipment at End Point Riser: Separator

Flowline Start Point Location Identification

Location ID: _____ Location Type: _____ Well Site
Name: ROCKWELL-61S69W Number: 1SENE
County: BOULDER No Location ID
Qtr Qtr: SENE Section: 1 Township: 1S Range: 69W Meridian: 6
Latitude: 39.994840 Longitude: -105.055840

Equipment at Start Point Riser: Well

Flowline Description and Testing

Type of Fluid Transferred: Multiphase Pipe Material: Carbon Steel Max Outer Diameter:(Inches) 2.375
Bedding Material: Native Materials Date Construction Completed: 12/09/1986
Maximum Anticipated Operating Pressure (PSI): 500 Testing PSI: 285
Test Date: 02/16/2018

OFF LOCATION FLOWLINE Abandonment Verification

Date: 10/08/2021

Abandonment Verification

The abandoned Off-Location Flowline was located within the jurisdiction(s) of the following local government(s).
(No Jurisdiction)

Description of Abandonment Verification:

The flowline serving the FCR MD 1-8 well (05-013-06130) was removed in its entirety. Approximately 72' of 2-inch steel flowline (buried +/- 4' deep) was removed. The excavation was backfilled and the land surface graded.

FLOWLINE FACILITY INFORMATION

Flowline Facility ID: 460503 Flowline Type: Wellhead Line Action Type: _____

OFF LOCATION FLOWLINE REGISTRATION

Equipment at End Point Riser: Separator

Flowline Start Point Location Identification

Location ID: 335728 Location Type: _____ Well Site
Name: FCR MD-61S69W Number: 1NENE
County: BOULDER No Location ID
Qtr Qtr: NENE Section: 1 Township: 1S Range: 69W Meridian: 6
Latitude: 39.998412 Longitude: -105.056779

Equipment at Start Point Riser: Well

Flowline Description and Testing

Type of Fluid Transferred: Multiphase Pipe Material: Carbon Steel Max Outer Diameter:(Inches) 2.375
Bedding Material: Native Materials Date Construction Completed: 08/31/1993

Maximum Anticipated Operating Pressure (PSI): 500 Testing PSI: 340

Test Date: 03/08/2018

OFF LOCATION FLOWLINE Realignment, Out of Service, Pre-Abandonment Notice, or Abandonment Verification

Date: 10/14/2020

Description of Realignment, Out of Service, Pre-Abandonment Notice, or Abandonment Verification:

Flowline/Riser is locked out and tagged out.

FLOWLINE FACILITY INFORMATION

Flowline Facility ID: 460499 Flowline Type: Wellhead Line Action Type: _____

OFF LOCATION FLOWLINE REGISTRATION

Equipment at End Point Riser: Separator

Flowline Start Point Location Identification

Location ID: 335728 Location Type: _____ Well Site
Name: FCR MD-61S69W Number: 1NENE
County: BOULDER No Location ID
Qtr Qtr: NENE Section: 1 Township: 1S Range: 69W Meridian: 6
Latitude: 39.998412 Longitude: -105.056779

Equipment at Start Point Riser: Well

Flowline Description and Testing

Type of Fluid Transferred: Multiphase Pipe Material: Carbon Steel Max Outer Diameter:(Inches) 2.375
Bedding Material: Native Materials Date Construction Completed: 08/16/1993
Maximum Anticipated Operating Pressure (PSI): 500 Testing PSI: 130
Test Date: 03/02/2018

OFF LOCATION FLOWLINE Realignment, Out of Service, Pre-Abandonment Notice, or Abandonment Verification

Date: 10/15/2020

Description of Realignment, Out of Service, Pre-Abandonment Notice, or Abandonment Verification:

Flowline/Riser is locked out and tagged out.

OPERATOR COMMENTS AND SUBMITTAL

Comments

This Form 44 is being submitted for one (1) Flowline Abandonment. The subject flowline was removed in its entirety. Details are as follows:

01306130FL

- Previously serviced the FCR -18 well (05-013-06130).
- Updated GIS SHAPEFILE is attached.
- Recent PRESSURE TEST is attached.


I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct and complete.

Signed: _____ Date: 11/03/2021 Email: nbennett@civiresources.com

Print Name: Nathan Bennett Title: Manager, W&L Permitting

Based on the information provided herein, this Flowline Report complies with COGCC Rules and applicable orders and is hereby approved.

COGCC Approved: _____



Director of COGCC

Date: 5/31/2022

Conditions of Approval

COA Type

Description

--	--

Attachment Check List

Att Doc Num

Name

402860957	Form44 Submitted
402860981	PRESSURE TEST
402860983	OFF-LOCATION FLOWLINE GIS SHP

Total Attach: 3 Files

General Comments

User Group

Comment

Comment Date

		Stamp Upon Approval

Total: 0 comment(s)